

# Rexroth PSx 6xxx.630 Timer And I/O Level

1070087079  
Edition 02

## Technical Information



**Title** **Rexroth PSx 6xxx.630  
Timer and I/O Level**

**Type of Documentation** Technical Information

**Type of documentation** DOK-PS6000-E/A630\*\*\*\*\*-FK02-EN-P

**Purpose of the documentat.** This manual provides information about

- the mechanical structure
- the electrical connection (24 V supply and I/O) and
- the functions

of the PSI/PST integrated weld timer.

**Follow-up of modifications**

Previous editions	Status	Comment
DOK-PS6000-E/A630*****-FK02-EN-P	05.2006	

**Note on ind. property rights** © Bosch Rexroth AG, 2006

Unless expressly authorized, any copying of this document and utilization and disclosure of its content is not allowed. Damages will be payable in case of contravention. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design (DIN 34-1).

**Legal validity** The data given in this document only intend to describe the product and must not be understood as guaranteed properties in the legal sense. We reserve the right to modify the contents of this Documentation and the availability of the products.

**Published by** Bosch Rexroth AG  
Postfach 11 62  
D-64701 Erbach, Germany  
Berliner Straße 25  
D-64711 Erbach, Germany  
Tel.: +49 (0) 60 62/78-0  
Fax: +49 (0) 60 62/78-4 28  
Dept.: BRC / PAW1

## Table of Contents

**Table of Contents**

	Page
<b>1</b>	<b>Safety Instructions . . . . . 1-1</b>
1.1	Possible Safety Markings on the Product . . . . . 1-1
1.2	Safety Instructions in this Manual . . . . . 1-2
1.3	Intended Use . . . . . 1-3
1.4	Qualified Personnel . . . . . 1-4
1.5	Installation and Assembly . . . . . 1-6
1.6	Electrical Connection . . . . . 1-9
1.7	Operation of the Product . . . . . 1-10
1.8	Retrofits and Modifications by the User . . . . . 1-11
1.9	Maintenance, Repair . . . . . 1-12
1.10	Working Safely . . . . . 1-13
1.11	CE mark . . . . . 1-14
<b>2</b>	<b>Overview . . . . . 2-1</b>
2.1	Type codes . . . . . 2-1
2.2	Features of PS 6000 series . . . . . 2-2
2.3	Programming and Operation . . . . . 2-5
2.4	Hardware Installation . . . . . 2-6
2.4.1	Timer front (without I/O module) . . . . . 2-8
2.4.2	Front of the I/O module "DEV-NET" . . . . . 2-10
<b>3</b>	<b>Timer Functions . . . . . 3-1</b>
3.1	Main Components of a Welding Station . . . . . 3-1
3.2	Types of welding modes . . . . . 3-2
3.2.1	Single Spot . . . . . 3-2
3.2.2	Seam mode . . . . . 3-3
3.3	Program schedule . . . . . 3-4
3.3.1	Programmable Current Blocks . . . . . 3-4
3.3.2	Impulse Mode . . . . . 3-5
3.3.3	Slope (Current Ramp) . . . . . 3-7
3.3.4	Programmable Times . . . . . 3-8
3.4	Regulation Modes . . . . . 3-11
3.4.1	Phase Angle (PHA) . . . . . 3-11
3.4.2	Constant Current Regulation (CC) . . . . . 3-12
3.5	Current Prewarning and Limitation . . . . . 3-14
3.5.1	Current Prewarning . . . . . 3-14
3.5.2	Current Limitation . . . . . 3-14
3.6	Monitoring . . . . . 3-15
3.6.1	Current Monitoring . . . . . 3-15
3.6.2	Timeout . . . . . 3-20
3.6.3	Time monitoring Monitor Stepper . . . . . 3-20
3.7	Interlock . . . . . 3-21
3.8	Measuring Circuit Test . . . . . 3-21
3.9	Limitation of the 1st Half Cycle (for PST only) . . . . . 3-22
3.10	Automatic Spot Repetition . . . . . 3-23

Table of Contents

3.11	Electrode Maintenance .....	3-25
3.11.1	Wear Factor and Wear per Welded Part .....	3-25
3.11.2	%I Stepper (Stepper) .....	3-27
3.11.3	Tipdressing of Electrodes .....	3-27
3.11.4	Prewarning and End of Stepper .....	3-28
3.11.5	Prewarning Table .....	3-28
3.12	Tip Replacement (Tip Wear Monitoring) .....	3-29
3.13	Electrode Force .....	3-29
3.14	Scaling .....	3-31
3.14.1	Force scaling .....	3-31
3.14.2	Current Scaling .....	3-33
3.15	Corrections .....	3-35
3.16	Weld Transformer Selection (PSI only) .....	3-35
<b>4</b>	<b>Technical data .....</b>	<b>4-1</b>
4.1	Integrated weld timer .....	4-1
4.2	I/O Module "DEV-NET" .....	4-2
<b>5</b>	<b>Electrical Connection .....</b>	<b>5-1</b>
5.1	Interference Suppression .....	5-1
5.2	Integrated weld timer .....	5-2
5.2.1	Output of the Internal 24 VDC Voltage Source (X4) .....	5-2
5.2.2	Supply of the Timer Logics (X4) .....	5-3
5.2.3	Supply of External Devices (X5) .....	5-4
5.2.4	24 VDC Voltage Distribution (X4) .....	5-4
5.2.5	Pressure Control and Feedback (X2) .....	5-7
5.2.6	KSR Sensor (X3) .....	5-9
5.2.7	Main switch trigger (X8) (only with PST) .....	5-11
5.2.8	Fan connection (X4) .....	5-13
5.2.9	Programming unit (X1) .....	5-13
5.3	I/O Module "DEV-NET" .....	5-14
5.3.1	Power Supply (X10) .....	5-14
5.3.2	DeviceNet Connection .....	5-16
5.3.3	Signal outputs and inputs .....	5-16
<b>6</b>	<b>I/O Signal Descriptions .....</b>	<b>6-1</b>
6.1	Input Signals .....	6-1
6.1.1	Alphabetical Overview .....	6-1
6.1.2	Start .....	6-2
6.1.3	Selection of program / spot .....	6-3
6.1.4	Automatic program selection active .....	6-4
6.1.5	Spot selection ready .....	6-4
6.1.6	Ignition on, external .....	6-5
6.1.7	Reset fault .....	6-6
6.1.8	Error Reset with WC .....	6-7
6.1.9	Error Reset with Spot Repeat / WC .....	6-8
6.1.10	Acknowledgement 'Tips Have Been Dressed' x .....	6-9
6.1.11	Acknowledgement 'Tips have been replaced' x .....	6-11
6.1.12	Acknowledgement 'Tips have been replaced' x .....	6-13

## Table of Contents

6.2	Output Signals .....	6-15
6.2.1	Alphabetical Overview .....	6-15
6.2.2	Prewarning Tip Replacement x .....	6-15
6.2.3	Tip Replacement x .....	6-16
6.2.4	Prop. Valve Selection .....	6-16
6.2.5	Sheet Thickness .....	6-17
6.2.6	Sheet Thickness Tolerance .....	6-17
6.2.7	Weld Complete (WC) .....	6-18
6.2.8	Control Ready .....	6-19
6.2.9	Welding faults .....	6-20
6.2.10	Weld/No Weld .....	6-21
6.2.11	Without Monitoring .....	6-21
6.2.12	Without Regulation and Without Monitoring .....	6-22
6.2.13	Automatic Program Selection Active .....	6-22
6.2.14	Tipdress Prewarning .....	6-22
6.2.15	Tipdressing Request x .....	6-22
6.2.16	Prewarning x .....	6-23
6.2.17	End of Stepper Electrode x .....	6-23
6.2.18	Spot Selection Taken Over .....	6-23
6.2.19	Status .....	6-24
<b>7</b>	<b>Maintenance .....</b>	<b>7-1</b>
7.1	Battery .....	7-1
7.2	Firmware .....	7-1
<b>8</b>	<b>Status and Error Messages .....</b>	<b>8-1</b>
<b>9</b>	<b>CE Declaration of Conformity .....</b>	<b>9-1</b>
<b>10</b>	<b>Timer Diagrams .....</b>	<b>10-1</b>
<b>A</b>	<b>Appendix .....</b>	<b>A-1</b>
A.1	Abbreviations .....	A-1
A.2	Index .....	A-2

Table of Contents

Notes:

# 1 Safety Instructions

The products described were developed, manufactured and tested in compliance with the fundamental safety requirements of the EU machinery directive. These products normally pose no danger to persons or property if used in accordance with the handling stipulations and safety notes prescribed for their configuration, mounting, and proper operation.

## Nevertheless, there is some residual risk!

Therefore, you should read this manual before installing, connecting or commissioning the products or programming the welding system. Store this manual in a place to which all users have access at any time!

The content of this manual refers to

- the mechanical structure
- the electrical connection (24 V supply and I/O) and
- the functions

of the PSI/PST integrated weld timer.

## The – according to the type of the product – integrated power supply units have their own manuals. They complete this manual!

- ★ Therefore, please pay attention to the following documentation as well:
  - For PST 6xxx:  
Thyristor power unit, technical information (1070 080 059)
  - For PSI 6xxx:  
Medium-frequency inverters, technical information (1070 080 058)

## 1.1 Possible Safety Markings on the Product



Warning of dangerous electrical voltage!



Warning of hazards associated with batteries!



Electrostatically sensitive components!



Lug for connecting PE conductor only!



Function ground, ground with low parasitic voltage



Connection of shield conductor only

## Safety Instructions

### 1.2 Safety Instructions in this Manual



#### **DANGEROUS ELECTRICAL VOLTAGE**

This symbol is used to warn of **dangerous electrical voltage**. The failure to observe the instructions in this manual in whole or in part may result in **personal injury**.

---



#### **DANGER**

This symbol is used wherever insufficient or lacking compliance with instructions may result in **personal injury**.

---



#### **CAUTION**

This symbol is used wherever insufficient or lacking compliance with instructions may result in **damage to equipment or data files**.

---

 This symbol is used to draw the user's attention to special circumstances.

★ This symbol indicates that an activity to be executed by you is described.

Modifications in this manual as compared to a previous edition are marked by black vertical bars in the margin.

## Safety Instructions

## 1.3 Intended Use

The product described

- serves in connection with a welding transformer and the appropriate power supply unit for
  - resistance welding of metalsand
- is suitable for operation in industrial environments in accordance with the following standards:
  - EN 50178
  - EN 50081-2
  - EN 50082-2
  - EN 60204-1

In residential environments, in trade and commerce as well as small enterprises class A equipment may only be used if it does not inadmissibly interfere with other equipment.

It is not intended for any other use!

**DANGER**

**Any non-intended use of the devices may cause injury to the user or third parties, as well as damage to the device, the workpiece to be machined, or to the environment.**

**Therefore, our products must never be used for any other than their respective intended purpose!**

---

- ☞ **For operation in residential environments, in trade and commercial applications and small enterprises, an individual permit of the national authority or test institution is required; in Germany, please contact the Regulierungsbehörde für Telekommunikation und Post (RegTP) or its local branch offices.**

The faultless, safe functioning of the product requires proper transport, storage, assembly and installation as well as careful operation.

## Safety Instructions

## 1.4 Qualified Personnel

The requirements as to qualified personnel are based on the requirement profiles defined by the ZVEI (Zentralverband Elektrotechnik und Elektronikindustrie – German Electrical and Electronic Manufacturers' Association) and the VDMA (Verband deutscher Maschinen- und Anlagenbau – German Engineering Federation) in:

**Weiterbildung in der Automatisierungstechnik**

**edited by: ZVEI and VDMA**

**Maschinenbau Verlag**

**Postfach 71 08 64**

**D-60498 Frankfurt.**

This manual is designed for technicians and engineers with special welding training and skills. They must have a sound knowledge of the software and hardware components of the weld timer, the power supply used, and the welding transformer.

Project engineering, programming, start and operation as well as the modification of program parameters is reserved to properly trained personnel! This personnel must be able to judge potential hazards arising from programming, program changes and in general from the mechanical, electrical, or electronic equipment.

Interventions in the hardware and software of our products, unless described otherwise in this manual, are reserved to specialized personnel. Tampering with the hardware or software, ignoring warning signs attached to the components, or non-compliance with the warning notes given in this manual can result in serious bodily injury or property damage.

Only skilled persons as defined in IEV 826-09-01 (modified) who are familiar with the contents of this manual may install and service the products described.

Such personnel are

- those who, being well trained and experienced in their field and familiar with the relevant standards, are able to analyze the work to be carried out and recognize any hazards.
- those who have acquired the same amount of expert knowledge through years of experience that would normally be acquired through formal technical training.



### **DANGER**

**An exception are persons with cardiac pacemakers!**

**The strong magnetic fields occurring in resistance welding may affect the proper functioning of pacemakers. This may be fatal or cause serious personal injury!**

**Therefore, persons with pacemakers must stay clear of resistance welding systems.**

**We recommend that warning signs as per DIN 40023 are posted at every entrance to manufacturing shops housing resistance-welding equipment.**

---

## Safety Instructions



**No entry for persons with cardiac  
pacemakers!  
Danger!**

Please note our comprehensive range of training courses. More information is available from our training center (Phone: +49 (60 62) 78258).

Safety Instructions

## 1.5 Installation and Assembly



**DANGEROUS ELECTRICAL VOLTAGE**

**Danger of life during installation work while systems are switched on!**

**Make sure that all plant sections undergoing operations during the installation are deenergized and sufficiently protected against accidental reclosing!**

---



**DANGER**

**Non-workmanlike installation or mounting may lead to personal injury or damage to property.**

**Therefore, it is essential that you take the technical data (environmental conditions) into account for installation or mounting. Installation or mounting must be carried out by skilled personnel only.**

---



**DANGER**

**Insufficient degree of protection may be life-threatening or cause damage to property!**

**The degree of protection of the products described is IP 20. They must be installed in switchgear cubicles providing a degree of protection of no less than IP 54.**

---



**DANGER**

**Danger of injury and of damage to property through incorrect installation!**

**Devices and, in particular, operating means, must be installed so as to be properly safeguarded against unintentional operation or contact.**

---



**DANGER**

**Danger of personal injury and damage to property through inadequate fastening!**

**The place for installing the modules, and their method of fastening, must be suitable for their weight!**

---

## Safety Instructions

**DANGER**

Injuries and bruises may be caused by lifting weights which are too heavy or by sharp metal edges!

Due to the weight of certain modules, their installation and assembly must be carried out properly and with suitable lifting equipment.

---

**DANGER**

The safety and accident prevention regulations as amended shall be observed!

Wear a protective helmet, safety shoes and gloves!

---

**CAUTION**

Short circuits!

When cut-outs are drilled or sawed in switchgear cubicles, metal burr may get into modules already installed there. Or, when cooling water lines are connected, water may leak into the modules installed.

The possibility of short circuits occurring in the process or even the destruction of the devices cannot be entirely ruled out.

Therefore, guard any existing modules well before you install a new module! Any and all warranty excluded in case of non-compliance.

---

**CAUTION**

Heat accumulation!

Modules must be mounted with a minimum clearance of 100 mm on top and at the bottom. Without this minimum clearance, heat may accumulate and cause inverter failure.

---

**CAUTION**

Leaks in the cooling water circuit may cause consequential damage!

Cooling water leaks may damage adjacent components. Therefore, when mounting watercooled modules, always ensure that other devices in the switchgear cabinet are well protected against leaking cooling water.

---

Safety Instructions

---



**CAUTION**

**Risk of damage to property by insufficient water quality in the cooling water circuit!**

**Deposits in the cooling system may reduce the water flow, thus impairing the performance of the cooling system with time.**

**Therefore, you should ensure that your cooling water has the following properties:**

- pH value 7 to 8.5
- Degree of hardness  $D_{\max}$  10 German degrees  
(1 German degree = 1.25 British degrees = 1.05 US degrees = 1.8 French degrees)

- Chlorides max. 20 mg/l
- Nitrates : max. 10 mg/l
- Sulfates max. 100 mg/l
- Insoluble substances : max. 250 mg/l

**Tap water usually meets these requirements. However, an algicide should be added.**

---

- ★ For information about dimensions and installation accessories of the product as a whole as well as information about the cooling system, please refer to the manuals of the power supply units (see page 1-1).

## Safety Instructions

## 1.6 Electrical Connection

---

**DANGER**

Danger of personal injury and damage to property through missing or false interpretation of fault messages!

Therefore, closing of the transformer temperature contact (thermostatic switch, break contact) must inhibit the connected timer! As regards fault analysis, see also section 8.

---

**DANGER**

Danger of life through inappropriate EMERGENCY-STOP facilities!

EMERGENCY-STOP facilities must be operative in all modes of the system. Releasing the EMERGENCY-STOP facility must by no means result in an uncontrolled restart of the system! First check the EMERGENCY-STOP circuit, then switch the unit on!

---

**CAUTION**

Connection or signal lines are to be laid out in such a manner that stray capacitive or inductive pick-ups do not affect any device functions!

In long lines, interference is often coupled and decoupled. Therefore, power and control cables must be routed separately. The effect of interfering cables on interference-sensitive ones can be minimized by maintaining the following distances:

- > 100 mm if cables are run in parallel for < 10 m,
- > 250 mm if cables are run in parallel for > 10 m.

Install the product close to the welding units to avoid cable lengths > 25 m wherever possible.

---

- ★ In addition, please comply with all safety regulations regarding electrical connections and the EMC of the system as a whole in the manuals of the power supply units (see page 1-1).
- ★ Make sure that all contact surfaces are bright, i.e. free of paint, plastic coating or dirt/oxidation.

Safety Instructions

## 1.7 Operation of the Product

---



**DANGER**

Magnetic field strengths that exceed the limit values according to VDE 0848 Part 4 must be reckoned with in the area of resistance welding systems. Limit values for extremities can be exceeded, especially in the case of manual tongs.

In cases of doubt, you should measure the field strength and take additional measures to ensure safety and health at work. Please comply with regulation BGV B11 of the German Berufsgenossenschaft (professional association) "Unfallverhütungsvorschrift elektromagnetische Felder".

---



**DANGER**

The strong magnetic fields occurring in resistance welding may affect the proper functioning of pacemakers. This may be fatal or cause serious personal injury!

Therefore, persons with pacemakers must stay clear of resistance welding systems.

We recommend that warning signs as per DIN 40023 are posted at every entrance to manufacturing shops housing resistance-welding equipment:

---



**No entry for persons with cardiac  
pacemakers!  
Danger!**

---



**DANGER**

Danger of personal injury and damage to property if devices are operated before they have been properly installed!

The devices are designed to be installed in housings or switchgear cabinets and must not be operated unless properly installed and switchgear cabinet doors are closed!

---

Safety Instructions

---

**DANGER**

**Danger of bruises through electrode movement!**

All users, line designers, welding machine manufacturers and welding gun producers are obliged to connect output signals which initiate the electrode movement so that the applicable safety regulations are complied with.

For example, by means of "Two-handed start", fences, light barriers etc. the risk of bruises can be considerably reduced.

---

**CAUTION**

**Overheating through inappropriate or insufficient cooling.**

The temperature inside the housing must stay within the specified range.

**Air-cooled medium-frequency inverters must always be operated under forced-air cooling conditions. Convection cooling will not be sufficient!**

**Air-cooled medium-frequency inverters must always be operated under forced-air cooling conditions. Condensation on water-carrying components must be prevented.**

---

## 1.8 Retrofits and Modifications by the User

---

**DANGER**

**Modifications to the product may endanger the safety of the unit! The possible consequences include death, severe or light injury (personal injury), damage to property or environmental hazards. Therefore, please contact us prior to making any modifications. This is the only way to determine whether changes can be made without any problems.**

---

Safety Instructions

## 1.9 Maintenance, Repair



### **DANGEROUS ELECTRICAL VOLTAGE**

**Prior to any maintenance work – unless described otherwise – the system must always be switched off and sufficiently secured! If required with the system being active, any measuring or testing work must be carried out by qualified electricians.**



### **DANGER**

**Lithium batteries can cause skin burns or explode in case of improper handling!**

**Therefore, do not forcefully open batteries, do not attempt to charge or heat up batteries over 100 degrees C!**



### **CAUTION**

**Please use only spare parts approved by us!**

**Use only original replacement batteries! In any case, spent batteries and accumulators should be disposed of as hazardous waste!**



### **CAUTION**

**Observe all precautions for ESD protection when handling modules and components! Avoid electrostatic discharges!**

The following protective measures must be observed for modules and components sensitive to electrostatic discharge (ESD)!

- The following protective measures must be observed for modules and components sensitive to electrostatic discharge (ESD)!
- Electrostatic discharge Personnel responsible for storage, transport, and handling must have training in ESD protection.
- ESD-sensitive components must be stored and transported in the prescribed protective packaging.
- Staff, worktables and all devices and tools coming into contact with electrostatic sensitive devices must be applied to the same potential (e.g. grounded).
- grounding Wear an approved grounding bracelet. The grounding bracelet must be connected with the working surface through a cable with an integrated 1 MΩ resistor.
- ESD-sensitive components must never come into contact with chargeable objects, including most types of plastics.
- When electrostatic sensitive devices are installed in and removed from a system, this system must be de-energized.

## Safety Instructions

**1.10 Working Safely****DANGER**

If the start signal is present on fault reset (acknowledge), the weld timer immediately starts the program sequence! Hazardous machine movements may be the result!

Therefore, before fault reset, you should make sure that there are no persons in the danger zone of the welding equipment!

---

**DANGER**

During operation of the welding equipment welding splashes are to be expected! They may cause eye injuries or burns.

Therefore:

- wear protective goggles
  - wear protective gloves
  - wear flame retardant clothes
- 

**DANGER**

Danger of injury from sheet metal edges and danger of burns from weld metal!

Therefore:

- wear protective gloves
- 

**CAUTION**

The strong magnetic fields occurring in the resistance welding process may cause permanent damage to wrist watches, pocket watches, or cards with magnetic stripes (e.g. EC cards).

Therefore, you should not carry any such items on you when working in the immediate vicinity of the welding equipment.

---

Safety Instructions

## 1.11 CE mark

---



### **CAUTION**

The CE mark for thyristor unit – welding transformer combinations (see section 9) refers to industrial applications.

For other combinations/applications, the certificate must be derived from the above or, if necessary, a new certificate must be issued. This is the duty of the line constructor / user.

The described product is an application variant that, due to its characteristics, cannot satisfy the regulations for terminals, machines or systems from the start. Therefore, it may be used only as described.

The electrical and mechanical safety and the ambient environment (foreign bodies, moisture) must be evaluated on the terminal when it has been installed.

The EMC characteristics of this product may change after it has been installed. As a result, a check of the EMC characteristics of the end product (terminals, machine, systems) by the manufacturer of the end product is advisable.

---

Overview

## 2 Overview

The PS 6000 series combines the following devices in one housing:

- Welding timer and
- Power supply unit.

The integrated weld timer is used for controlling the integrated power supply unit and is suitable for


- Spot welding (e.g. in connection with a robot)
- Projection welding
- Repeat mode (e.g. manual welding guns) and
- Seam welding (e.g. roll seams).

In addition to a **variation of timers** whose main differences lie in their I/O connection to the higher-level PLC/robot unit and in their functionality, there are also

**different power supply units** (MF inverters/thyristor power supply units) with different cooling systems (air/water) of several different performance classes available for controlling the welding transformers.

### 2.1 Type codes

The product name contains information about the corresponding product variation:



*Type code of PS 6000 series*

## Overview

## 2.2 Features of PS 6000 series

 **For information about dimensions, mains connection, cooling or welding current, please refer to the manual of the power supply unit in use (see page 1–1).**

- User interface for operation, programming and diagnosis:
  - Standard: complete for graphic user interface BOS-5000; runs on PCs with Windows 95/98, NT4, or W2000 operating system.
  - Optional and with limited functions: via operating and diagnostic terminal BT 220 with PLC function (CL 500) or BT 6. Connection: via V24.
- Optional access limitation for operation/programming
  - By password (interlocking disk)
- Programming connection to PC (BOS-5000):
  - Standard: for an individual control via V24 (e.g. for programming on location)
  - Optional: contemporary connection of more than one timer via field-bus interface:
    - PROFIBUS-FMS
    - INTERBUS-PMS
    - Ethernet
- I/O connection (communication with e.g. robot/PLC):  
Available connections:
  - parallel (discrete I/O wiring)
  - serial (via bus system):
    - PROFIBUS DP
    - INTERBUS S
    - DeviceNet
- Number of programs:
  - Maximum of 256 programs; symbolic spot addressing possible. Because of the great number of programs, in most cases it is possible to assign a program to each weld spot.
- Programming of times (depends on integrated power supply unit):
  - AC technology: in line cycles
  - MF technology: in milliseconds
- Universally adaptable welding schedule:
  - 3 programmable weld times (1. WLD: preheating weld time; 2. WLD: weld time; 3. WLD: postheating weld time).  
The welding times can be operated either together in one regulation mode (standard operation) or in different regulation modes (mixed operation).
  - The 1.WLD and 3.WLD can be turned off
  - Programmable impulse mode for 2. WLD
  - Programmable slope mode (current rise/decay time) for 2. WLD
- Types of welding modes:
  - Spot welding (e.g. in connection with robots)
  - Repeat mode (e.g. in connection with manual guns)

## Overview

- Roll seams
- Half cycle operation
- Regulation modes:
  - PHA (Phase angle)
  - CC (Constant Current Regulation)Mixed operation for individual welding times is possible.
- Current monitoring:
  - Reference currents are programmable independently from the regulation command values
  - Tolerance band in percent, asymmetrically programmable
  - Monitoring in standard and mixed mode possible
- Automatic spot repetition in case of low current
- Timeout
- Electrode Management:
  - Stepper function for current (current stepping)
  - Tips have been dressed incl. initial dressing
  - Stepper function for force (stepping of electrode force)
  - Prewarning table with graphic representation of electrode wear
- Proportional valve control:
  - Output signal is high after program selection
  - Analog and digital pressure control
  - Feedback possible
  - Electrode force programming in kN for all welding programs
  - Force scaling for adaptation to the valve characteristic curve
- Force profile:
  - up to 10 different electrode forces can be programmed during the execution of a program
- External weld time termination on halfwave
- Freely programmable output:

Up to 3 turn-on/-off times can be programmed during the sequence of a program. Serves e.g. to control a backpressure valve or for weld spotsynchronous preparation of components that are subject to welding.
- Scaling programs:
  - for current (adjustment of the welding device with regard to an external reference ammeter)
  - for force (adjustment of the electrode force with regard to an external reference dynamometer)
- Protocol function (ISO 9000):
  - Error Protocol
  - Weld Fault Protocol
  - Data Change Protocol
  - Weld Current Protocol

## Overview

- Integrated diagnostic memory
- Fault allocation:
  - Events are programmable either as errors or warnings.
- Status display of I/O signals in online mode
- %I correction:
  - for selected programs
  - for all programs
  - for selected programs
- General overview of system for:
  - Start inhibit
  - Ignition on, internal
  - Timeout
  - Current monitoring
  - 2. WLD in PHA/CC
  - Program-related electrode number
- Upload/Auto-Upload (Data backup)
- Restore (Data restoration)
- Copy of welding programs
- Exchange of timer (data backup and restoration of entire module, including counter content and actual values)
- Start simulation:
  - Program selection and start of schedule can be initialized via GUI
- Available languages:
  - German
  - English
  - NA English
  - Spanish
  - French
  - Swedish
  - Portuguese
  - Italian
  - Hungarian
- Online and offline programming possible
- Prepared for upgrade with an optional quality module or for extension with an optional ultrasonic control board (USR).

Overview

## 2.3 Programming and Operation

All necessary parameters will be stored in the timer's internal battery-buffered RAM.

Operation, programming, and diagnosis are handled via the connected PC. The PC can be either connected via

- the timer's V24 interface (X1) or via
- an optional fieldbus interface (e.g. PROFIBUS).

While the V24 connection allows for access to a single timer only (e.g. programming on location), the fieldbus interface allows for the contemporary connection of more than one timer.

Prerequisites for programming and operation via PC:

- Operating systems Windows95/98, NT4 or W2000
- Software BOS-5000 ("BedienOberfläche Schweißen" = GUI Welding)
- V24 connecting cable or in case of fieldbus interface corresponding installation.

☞ **For detailed information about BOS-5000, please refer to the BOS-5000 manual.**

☞ **With regard to time programming, PSI and PST differ from each other:**

**PSI: spacing in 1 ms**

**PST: in line cycles**

**(at 50 Hz: 1 line cycle corresponds to 20 ms)**

**(at 60 Hz: 1 line cycle corresponds to 16.6 ms)**

☞ **The timer can be programmed "online" as well as "offline".**

- offline:

An active connection to the timer is not necessary.

Diagnosis and visualization are not possible.

The programming is handled and saved on the PC and can be transferred to the timer at a later point in time.

- online:

An active connection to the timer is necessary.

Diagnosis and visualization are not possible.


The programming is handled via PC. Each parameter will be read out and, after acknowledgement, written back to the timer. This way, modified and acknowledged parameters will be effective with the system's next program start at the latest.

## Overview

## 2.4 Hardware Installation

The timer module is fastened to the right side of the global housing. In addition to the standard display and operating elements and terminals, it contains

- type-specific I/O module:  
for connection of the timer to the higher-level PLC or the robot (these are preinstalled on delivery and will function only with the appropriate control firmware).
- one slot for the optional fieldbus module:  
for programming/operating/diagnosing the weld timer via fieldbus
- a slot for an optional quality module or for extension with an optional ultrasonic control board (USR).



☞ **The dimensions of the global housing and the functional units for cooling depend on the size of the integrated power supply unit and can be slightly different than the above illustrated example.**

★ For installation and mounting, please refer to the corresponding manuals of the power supply unit in use (see page 1-1).


## Overview

**CAUTION****Risk of malfunction and damages!****Incorrect installation, connection, or operation can provoke unexpected or erroneous reactions of the device, which may lead to dangerous situations in the welding station.****Please comply with all instructions in the manuals.**

---

Overview

### 2.4.1 Timer front (without I/O module)



## Overview

 **For Technical data of the timer, please refer to chapter 4.1 on page 4-1.**


**CAUTION**

**Immediately upon pushing the "boot" button, welding processes become impossible! The timer interrupts the program sequence, switches all signal outputs to 0 V and goes into "boot" mode (for firmware exchange). The button shall**

- never be pressed during operation and**
  - may be pressed by authorized personnel only.**
-

Overview

## 2.4.2 Front of the I/O module "DEV-NET"



For technical data of the I/O module, please refer to chapter 4.2 on page 4-2.

## 3 Timer Functions


### 3.1 Main Components of a Welding Station

Welding stations that are equipped with PS 6000 generally consist of the following main components:

- Weld timer with integrated power supply unit (in AC or MF technology; AC: thyristor power supply unit; MF: medium-frequency inverter)
- suitable weld transformer with current sensor and
- pneumatically or electrically driven gun, electrodes included.

In addition, an upstream control that controls the entire process regarding the work piece and monitors its safety is necessary. This can be provided by e.g.

- a programmable logic controller (PLC)
- robot control, or
- a combination of the above.




Main components of a welding station

The weld timer ensures the controlled flow of the actual welding process. In order to do so, it must control and regulate a great number of functions and physical variables. Main tasks are e.g.

- the communication with a higher-level PLC or robot control via I/O signals
- triggering a proportional control valve or a servomotor in order to influence the electrode force
- making sure that the different times are scheduled correctly (e.g. squeeze, current, hold time etc.)
- controlling the power supply unit to produce a correct welding current

Timer Functions

- indicating either a correct or erroneous weld at the end of the welding program.



Physical variables for affecting the weld

### 3.2 Types of welding modes

In order to execute a welding process, the timer can be operated via PLC / robot or controlled manually by an operator.

To this end, the PS 6000 provides for different welding modes:


- Single spot mode
- Seam mode.

#### 3.2.1 Single Spot

Appropriate for utilization in connection with robots, welding machines, automatic welders and hand tongs; for spot welding, projection welding, butt welding.

A "high" level at the START input (see also page 6-2) starts the welding process (welding program) exactly 1x – starting with the 1.SQZ. At the end of the program, the timer outputs the WELD COMPLETE (WC) output signal, as long as no welding error has been detected. For a new welding process, the start signal has to be toggled off/on.

## Timer Functions



*Welding operation mode single spot, signal schedule*

### 3.2.2 Seam mode

Suitable for roll seam stations.

With this technique, you pass over the welded parts with rolling electrodes and the parts are connected by individual spot welds.

As in single spot mode, the weld timer reacts to the start signal and starts the welding process.


The weld time (2.WLD) and a possibly programmed cool time (2.CT) will be repeated, as long as the high level at the START input is pending.

If the start signal changes to low level, the timer interrupts the flowing current impulse and starts the hold time (HLD).

Seam mode is divided in stitch and seal welds:

**Stitch weld:** Successive weld times are separated from each other by sufficiently rated cool times, so that successive spot welds neither touch each other nor overlap.

**Seal weld:** The cool time is so short that successive spot welds overlap.



*Seam mode*

Timer Functions

### 3.3 Program schedule

There are 256 different welding programs (program no. 0 – 255) available. First, select the program via the program selection inputs (refer to page 6-3), then start the welding process via high level at the START input (see also page 6-2).

Each welding program contains all parameters necessary for the exact definition of a weld. Basic parameters are e.g.

- Currents that are to be effective in different current blocks (refer to chapter 3.3.1 ff)
- Times that are supposed to run consecutively (please refer to chapter 3.3.4, page 3-8 ff)
- Electrode force (for further explanations, please refer to page 5-7).

#### 3.3.1 Programmable Current Blocks


The process may require to produce the heat necessary for a single spot weld in consecutive current blocks.

Therefore, you can execute a spot weld using up to three current blocks (1. WLD, 2. WLD, 3. WLD). With regard to its time and current, each block can be programmed separately.

 **Programming the currents depends on the active regulation mode (refer to page 3-11):**

**PHA (Phase angle):** in scale values  
**CC (Constant Current Regulation):** in kA

Between the blocks, cool times can be programmed (1.CT, 3.CT). If you set a cool time = 0, the two corresponding blocks lie seamlessly next to each other.



Available current blocks

## Timer Functions

### 1.WLD (1st weld time / pre-heating time):

With this current block, you can preheat the metal with a smaller current (1.%I) prior to the actual welding process (in the 2nd current block), in order to reduce the risk of e.g. welding splashes.

If you do not want to use the 1.WLD, simply set 1.WLD = 0.

### 2.WLD (2nd weld time / 2<sub>nd</sub> current block):

With this current block, you actually weld a spot with the command current (2.%I).

- The 2nd weld time must always be programmed.
- Within the 2.WLD, the functions:
  - "Impulse mode" (refer to page 3-5) and
  - "Slope" (refer to page 3-7) are available.

### 3.WLD (3rd weld time/ post-heating time):

With this current block, you can heat the metal with a smaller current (3.%I) after the actual welding process (2nd current block).

This compensates e.g. for too rapid cooling of the spot welds caused by the electrode's cooling. It improves the structure of the welded part and serves to relieve weld stresses.

If you do not want to use the 3.WLD, simply set 3.WLD = 0.

## 3.3.2 Impulse Mode

In addition to the possibility to distribute the heat necessary for one single spot weld on 3 successive current blocks (refer to page 3-4), you also have the **impulse mode** at your disposal.


Within the **2nd current block**, the heat necessary for welding a spot can be distributed on up to 9 successive impulses which reduce the risk of welding splashes as well.

Between the impulses, you can program a 2.CT.

If you set the 2.CT = 0, all impulses lie seamlessly next to each other.

Timer Functions

You can set the impulse mode via parameter "Impulse".  
 This parameter determines how often the 2.WLD will be repeated taking into consideration a programmed 2.CT.



## Timer Functions

### 3.3.3 Slope (Current Ramp)


If the Slope function is activated, the timer independently produces a linear current increase (upslope) or decrease (downslope) for the **2nd current block** within a programmable time span. The Slope function reduces the switch-on current peak and thus the stress on the welding station.

For programming, use

- **current upslope time (UST)** to determine the time span in which the momentary current shall be increased from "starting current" to the command current of the 2.WLD (2.%I), or
- **current downslope time (DST)** to determine the time span in which the command current of the 2.WLD (2.%I) shall be reduced to the "final current". DST (current downslope time)

Please note:

- Current upslope and downslope times are always part of the 2nd current block.  
The current upslope time starts with the beginning of the 2nd current block.  
The current downslope time ends with the end of the 2nd current block.
- Current upslope and downslope times are not influenced by an activated impulse mode or a possibly programmed 2.CT. I.e. they ignore a possible 2.CT and proceed.
- If the sum of UST and DST is larger than the 2nd current block, the command current in the 2nd block (2.%I) will never be reached! Fault messages as e.g. "current too low" appear.
- Please use, in connection with the slope, the fade-out time (refer to page 3-18).



Example: Slope in connection with impulse mode

Timer Functions

### 3.3.4 Programmable Times

The schedule of a welding program depends on the use of different programmable time spans. Each time span serves a certain purpose within the program schedule.


☞ **With regard to time programming, PSI and PST differ from each other:**

**PSI: spacing in 1 ms**

**PST: in line cycles**

**(at 50 Hz: 1 line cycle corresponds to 20 ms)**

**(at 60 Hz: 1 line cycle corresponds to 16.6 ms)**



Example of a time diagram with all programmable time spans



## Timer Functions

### **2.WLD (2nd weld time)**

Refer to page 3-5.

### **2.CT (2nd cool time)**

If programmed with a value greater than 0, will separate the individual impulses with impulse mode. Is used to relieve stress from the welded part.

Refer to page 3-5.

 **The 2.CT can only be programmed if the impulse mode is activated (parameter "impulses" > 1).**

### **UST (Upslope time / Current upslope time)**

Refer to page 3-7.

### **DST (Downslope time / Current downslope time)**

Refer to page 3-7.

### **3.WLD (3rd weld time / post-heating time):**

Refer to page 3-5.

### **3.CT (3rd Cool time)**

If programmed with a value greater than 0, will separate the second from the third current block. Is used to relieve stress from the welded part.

Refer to page 3-4.

 **The 3.CT can only be programmed if the 3.WLD is larger than 0.**

### **HLD (Hold time)**

Is used, in order to fix the welded part during cooling. Current has stopped flowing in this time segment.

At the end of the HLD, the welding gun opens up. If there hasn't been detected any welding fault, the output signal WELD COMPLETE (WC) will be output (refer to page 6-18).

## 3.4 Regulation Modes

The weld timer provides the following regulation modes:

- Phase angle (PHA) and
- Constant Current Regulation (CC).

The allocation between program and regulation mode is very flexible. Thus, two different regulation possibilities are available:

- **Standard operation:**  
A regulation mode can be assigned to every welding program. The set regulation mode is valid for all weld times of the program.
- **Mixed operation:**  
Different regulation modes can be assigned to the program's weld times.

 **Regulation and monitoring are separate functions! This is why the current command values are separately parameterizable for regulation and monitoring.**  
**Please refer to chapter 3.6.1, page 3–15 ff.**

### 3.4.1 Phase Angle (PHA)

Special case.


The operation mode PHA doesn't provide for the regulation of an actual variable (e.g. current), but triggers exclusively the power supply unit. In the PST, this causes a triggering of the thyristors during the sinusoidal half-wave (el. firing angle: 130 degrees to 30 degrees; the larger the firing angle, the less current flows in the secondary circuit); in the PSI, you can thus influence the pulse width.

#### Features PHA:

- Currents are programmed in scale values (%I).  
Programmable range: 0.0 to 100.0 scale values.  
Programming resolution: 0.01 scale values
- No regulation.
- The resulting current intensity in the secondary circuit depends on the transition resistance electrode/welded part, and the secondary voltage.
- A current sensor for measuring the actual current is not necessary.

 **Current and time monitoring can be enabled in PHA mode. Current monitoring though requires a current sensor (toroid). Mains**

Timer Functions



Principle of the unregulated PHA operation

### 3.4.2 Constant Current Regulation (CC)


Standard case (e.g. with robot guns).

In CC mode, current regulation is activated. The actual current is measured and continuously compared to the programmed command current. A series-connected controller processes the difference between the command and the actual value and controls the phase angle/the pulse width in the power supply unit in order to reach the command current.

## Timer Functions

**Features CC:**

- Currents are programmed in kilo Ampere (kA).  
Programmable range: 0.5 to 250 kA  
(can be limited by parameterization and the power supply unit in use).  
Programming resolution: 10 A.
- The current in the secondary circuit is regulated.
- Eliminates the influence of the electric resistance on the weld process in the secondary circuit (e.g. electrode/welded part contact resistance).
- A current sensor is absolutely necessary for measuring the actual current (please refer to page 5-9).



*Principle of the CC regulation mode*

## 3.5 Current Prewarning and Limitation

### 3.5.1 Current Prewarning

Via the "Current prewarning" parameter it is possible to indicate,

- from which scale value on the message "Phase Angle Prewarning has been reached" will be displayed.

This way, in CC regulation mode, the timer can indicate e.g. an imminent current limitation, caused by e.g. cable losses in the secondary circuit.

- ☞ **The parameter value must be smaller than the current limitation value.**

### 3.5.2 Current Limitation

- ☞ **At first, parameterize the current prewarning.**

Via the "current limitation" parameter, you determine the minimum phase angle (electric degree)

- in CC mode by the controller's command value and
- in PHA operation via programming.

To do so, please program the highest permissible scale value.

If the current limitation function reacts, the timer sends the message "maximum phase angle".

- ☞ **The input value for the current limitation is absolute!  
Therefore, the "%I correction" function (see page 3-35) and the "stepper" function (see page 3-27) might lead to an activation of the current limitation.**

- ☞ **The parameter value must be greater than the current prewarning.**

## 3.6 Monitoring

The timer can monitor welding processes with regard to the following variables:

- Current (please refer to chapter 3.6.1) and
- Time (please refer to chapter 3.6.2, page 3–20 ff).

Both monitor modes can be switched on and off separately.

Activated monitorings check the relevant actual value in comparison to the programmed reference values and tolerance bands.

Since the variables current and time affect the heat within the spot, correctly set reference values and activated monitorings are essential measures and prerequisites for quality assurance.

-  **The reference values used for monitoring can be programmed independently from the regulation parameters. A modification of the command values for regulation (closed-loop control) does not affect the monitoring parameters! Corresponding access rights allow the operator to set new reference values manually or accept a previously measured actual value as a new reference value.**

### 3.6.1 Current Monitoring

-  **A current sensor is absolutely necessary for measuring the actual current (please refer to page 5–9).**


#### Tolerance Range

Current monitoring compares the actual current that has been measured by means of the r.m.s. value with the "tolerance band".

It depends on the programmed tolerance band whether the timer identifies the measured actual current as "good" or not. The following values are decisive for the definition of the tolerance band:

- Reference current in kA
- Positive tolerance in % of the reference current (permissible upper tolerance band).  
Actual values above the upper tolerance band lead to the message "Current too high...".
- Negative tolerance in % of the reference current (permissible lower tolerance band).  
Actual values below the lower tolerance band lead to the message "Current too low..." or "No current...".

Timer Functions



Principle: Tolerance band

**Conditional permissible tolerance band**

In addition to a "good/bad" statement, it is often desirable to be informed about the trend of the actual current values in time. In this regard, slow but continuously increasing actual current values in the lower segment of the tolerance band are especially interesting: Slowly developing errors in the system (e.g. slowly increasing cable resistance within the measuring circuit prior to a cable break) can lead to such effects. It is also possible that not perfectly set reference current values are the cause for actual current values in the lower segment of the tolerance band.


Therefore, the following additional parameters are at your disposal in connection with the tolerance band:

- "Conditional permissible tolerance band" (in % of the reference current) and
- "Repeat factor".

The parameter "conditional permissible tolerance band" determines the upper limit of the conditional permissible tolerance range. The lower limit is defined via the parameter "permissible lower tolerance band".

The "repeat factor" determines, how many **consecutive** spot welds may lie in the conditional permissible tolerance range.

If this value is exceeded, the timer sends the message "Current too low for a series of welds".



Example: Principle of the Conditional Tolerance Band with Repeat Factor = 4

## Timer Functions

- ✎ **Messages can be defined either as a "welding fault" or as a "warning". An event that has been defined as a "warning" does not lead to a blocking of the timer. A "welding fault" though always requires a "Fault reset" (see page 6–6) in order to start the next welding process.**

### Current monitoring modes

Since there are 3 programmable independent current blocks (refer to page 3–4), current monitoring should be flexible and easy to handle. Therefore, the two different monitoring modes "Standard" and "Mix" are available.


- **Standard operation:**

The entire current profile (1st, 2nd, and 3rd current block, cool times included) is part of the r.m.s. value measurement.

Here, the complete current profile is represented by only one actual value and monitored by only one tolerance band.

Because of this simple, but most of the time sufficient monitoring mode, the quantity of data to be processed remains small, but possible cool times and different currents within the individual blocks change the measurement result.

In this case, the reference current should be measured via sample welds. If you use the 2.WLD only and no impulse mode, you can enter the command current programmed for the regulation as the reference current.



*Principle of the monitoring mode "Standard"*


- **Mixed operation:**

The r.m.s. value will be measured separately for each current block and monitored by the current blocks' own tolerance bands (for 1st, 2nd, and 3rd current block). Programmed cool times are not taken into consideration when calculating the actual value for each current block.

This leads to a better transparency for the single current blocks, but the quantity of data to be processed is larger.

In mixed operation, you can always use the command currents programmed for regulation as the reference currents.

## Timer Functions



Principle of the monitoring mode "Mix"

### Fade-out time and trail current

The above descriptions of the current's temporal schedule are ideal cases (rectangular form). In reality though, the current recovers and decays at the beginning and the end of a weld time. These effects have an influence on the r.m.s. value measurement.

With the functions "Fadeout time" and "Trail current", you can affect the measurement specifically.

- **Fade-out time:**

Indicates, for how long after the start of a weld time, measured current values are **not** to be taken into consideration for the calculation of the r.m.s. value. This way, if set correctly, you can fade out the entire transient recovery process.

Use of fadeout time:

- in connection with the "Slope" function (refer to page 3-7): please program the same value for the fade-out time as for the current upslope time (UST);
- when welding thick sheets and when the use of a deeply immersing welding gun (gun reaches far into the material) is necessary;
- in connection with current scaling: Measuring instruments for the reference welding current are provided with a "fade-out function" as well (e.g. Miyachi: "First Cycle"; indication from which cycle of the weld time on measured values shall be taken into consideration).


For current scaling, make sure that the measurement instrument in use is set to the timer's currently parameterized fade-out time.

- **Trail current:**

Indicates if the decaying process after the end of the weld time shall be taken into consideration for the calculation of the r.m.s. value (trail current ON).

In connection with fade-out times higher than "0", this may result in the determination of too low r.m.s. currents when calculating the measured value, even though the absolute command current in steady state has been reached.

## Timer Functions




*Fadeout time and trail current*

The programmed fadeout time always starts

- at the beginning of a current block
- at the beginning of an impulse.

An activated trail current always starts

- at the end of a current block
- at the end of an impulse.



*Starting points of the fadeout time and the trail current*

☞ **The programmed fadeout time is identical for all weld times and for all welding programs!**  
Therefore, please make sure that the fade-out time is always smaller than the smallest programmed weld time.

☞ **An active trail current applies to all weld times and welding programs.**

## Timer Functions

☞ **If for your application the only quality criteria is the heat introduced into the spot weld (heat:  $Q \approx i^2 \times t \times R$ ), please program the fade-out time with the value "0" and switch ON the trail current.**

### 3.6.2 Timeout


Time monitoring is separately adaptable to each program and compares the actual time necessary for the complete current profile to a programmed reference time.

As actual time we understand the time span from the beginning of the first current block till the end of the last current block, cool times included.

This way, you can avoid the execution of excessive weld time changes in the individual welding programs.

The following values are decisive for programming the time monitoring function:

- Time monitoring ON/OFF
- Reference time
- Permissible time deviation from the programmed reference time.  
Actual times above the permissible time deviation lead to the message "Weld time too long...".  
Actual times below the permissible time deviation lead to the message "Weld time too short...".



*Principle of the timeout function*

### 3.6.3 Time monitoring Monitor Stepper

☞ **A current sensor is absolutely necessary for measuring the actual current (please refer to page 5-9).**

It serves when executing the electrode maintenance functions

- "Stepper" (refer to page 3-27) and
- "Tip dressing" (see page 3-27)

## Timer Functions

for monitoring the programmed %I stepper.

This way, you can avoid the execution of excessive changes in the individual stepper or tipdressing curves.

With an activated stepper, the timer changes the programmed command current in dependence of the electrode wear.

The "Monitor Stepper" gives you the possibility to program, separately for each singular stepper or tipdressing curve, stepper values in percent which then will be taken into consideration as reference values for the monitoring process.

### 3.7 Interlock

In the welding operation mode "single spot", the timer goes into "Interlock" upon the end of the SQZ. While in "Interlock", the 1., 2., and 3.WLD and the HLD are processed even after the input signal "Start" has been reset.

☞ **"Interlock" can be interrupted only by opening the stop circuit (see page 5-15).**

☞ **In the welding operation mode "seam mode", there is no "Interlock". If the input signal "Start" is reset during a weld time, the timer terminates the cycle that has just begun and continues with the hold time.**

For more information regarding "Interlock", please refer to input signal START on page 6-2.

### 3.8 Measuring Circuit Test

This function checks the measuring circuit for interruptions and short circuits during the squeeze time (see page 5-11). This way, errors in the cables/current sensor can be detected in time.

If an error is detected, the weld timer interrupts the current welding program before entering the first programmed weld time and generates a corresponding message ("measuring circuit open" or "short circuit in measuring circuit").

To activate the function, switch parameter "Measuring circuit test" to "On".

**Conditions:**

- The parameter "monitoring stopped" is switched off **and**
- the function "current monitoring" (refer to page 3-15) is activated.

## Timer Functions

 **Messages can be defined either as a "welding fault" or as a "warning". An event that has been defined as a "warning" does not lead to a blocking of the timer. A "welding fault" though always requires a "Fault reset" (see page 6–6) in order to start the next welding process.**

**CAUTION****Risk of too high weld current!****Both messages must always be defined as a "fault".****Otherwise the controller receives no or erroneous information about the actual value. This might result in the controller triggering the power supply unit fully.****After 40 ms at the latest, the welding schedule will be interrupted with the message "weld time termination/no current" ("no current": refers to the measured actual value).**

### 3.9 Limitation of the 1st Half Cycle (for PST only)

The activation of the first current half cycle can be limited in order to protect the weld transformer and the thyristor power supply unit.

Example: A command value of 55 scale units means that

- in welds with smaller command currents (0 to 55 scale units), the 1st half cycle is not affected
- with higher command currents (> 55 scale units), the 1st half cycle is limited to 55 scale values.

For programming you have 2 parameters at your disposal:

- "Limit 1. half cycle":  
Parameter affecting the entire module.  
Only the first half cycle of a weld is limited.
- "1. Halfcycle after cool time":  
Can be set separately for each welding program.  
The first half cycle of each weld time or each impulse is limited if previously a cool time has been programmed > 0.

### 3.10 Automatic Spot Repetition

This function serves to reduce necessary user intervention in the case of occasional "current too low..." or "no current..." welding faults.

Conditions:

- Current monitoring is active, **and**
- the function "monitoring stopped" is switched off.

The function "Automatic spot repetition" can be switched on and off separately for each welding program via the parameter "Spot Repeat".

If the automatic spot repetition is activated, the timer is able to repeat – starting with the SQZ – an erroneous welding process automatically once, in case of a "current too low..." or "no current..." message. In this case, the gun remains closed after the erroneous process and programmed squeeze time, weld times, and hold times are repeated.


If the repetition results in a correct weld, the welding station will then resume its normal operation. If during repetition, another error is detected, a corresponding message will be displayed ("Current too low...", "no current...").

If automatic spot repetition is activated, bad fittings or not perfectly lying electrodes might lead in extreme cases to a repetition of each single spot weld. I.e.: the clock time might increase very fast and maybe even unnoticed.

Therefore, the timer provides the parameter "Max. repetition" (highest permissible amount of spot repetitions in sequence).

An internal counter is always reset to 0 if a weld is successful at first attempt. Otherwise, if the value falls below the "permissible lower tolerance band" and the automatic spot repetition is activated, the counter will be incremented.

Automatic spot repetition will only take place if the internal counter value is smaller/equals the "max. repetition" parameter. If this is not the case, the timer generates the message "Current too low for a series of welds".



*Example: Principle of the automatic spot repetition with "max. repetition" = 4*


## Timer Functions

 **Messages can be defined either as a "welding fault" or as a "warning". An event that has been defined as a "warning" does not lead to a blocking of the timer. A "welding fault" though always requires a "Fault reset" (see page 6-6) in order to start the next welding process.**

Timer Functions

## 3.11 Electrode Maintenance

During their life, electrodes are subject to a process-related wear (see chapter 3.11.1) which can be noticed by e.g. an enlargement of the electrode's contact point.



*Enlargement of the contact point by electrode wear*

To compensate for this effect, the timer provides two different procedures:

- "Automatic stepper" (refer to page 3-27) and
- "Tip dressing" (see page 3-27)

Both procedures can be activated either separately or combined.

### 3.11.1 Wear Factor and Wear per Welded Part

The wear of the electrodes depends on different factors, like e.g. programmed current, thickness and material of the welded part.

As long as you perform welds of only one type of material with the same thickness and the same current during the life of an electrode, it can be easily predicted, after how many welds the electrode is worn and must be exchanged. The electrode wear can be displayed by means of a "spot counter". The spot counter will be incremented by "1" after each performed welding process.

If the parts that are welded during an electrode life consist of different materials or different gauges, the wear per spot weld is not constant. In this case, a spot counter is not sufficient anymore.

Therefore, the wear of an electrode in the timer is monitored via a "wear counter".

To this end, the control increases the wear counter after each welding process by the "wear factor". The wear counter cannot only be incremented by "1" (as for the spot counter), but by any value.

Since you can enter the right wear factor for the weld in each program, a correct measurement of the electrode wear is guaranteed.

#### **Wear per part**

Via the parameter "Wear/Part" you can enter the electrode wear that is caused by the welding process of one single piece. With this variable, the

## Timer Functions

timer can calculate how many pieces can be welded with the electrode until the end of stepper (maximum electrode life). The amount of the remaining parts will be displayed in the "Prewarning table" (see page 3-28).

**Example:**


6 welds must be performed on a part.

Each spot weld (P1 to P6) is produced by a separate welding program (Prog1 to Prog6).

For the upper spots (P1 to P3), 2 sheets must be welded, for the lower 3 spots (P4 to P6) 3 sheets.

The electrode wear for the spot welds P4 to P6 is higher (thicker material). Therefore, the program-specific wear factor in Prog1 to Prog3 must be programmed with "1", while the wear factor in Prog4 to Prog6 is "1.5". The wear per piece is therefore 7.5.


 **The wear factors in this example have only exemplary meaning. In reality the wear factors for the materials and gauges in use will be calculated in advance.**



*Example: Calculation of the wear*

### 3.11.2 %I Stepper (Stepper)

The stepper function keeps the current density in the spot weld constant while during the electrode's life, the spot weld becomes larger and larger. To do so, you can define separate stepper curves for up to 10 different electrode types. A stepper curve determines the percentage with which the programmed command current should be increased automatically in dependence of the current electrode wear.



Principle: %I stepper

☞ **The resulting current changes can be monitored by means of the "Monitor Stepper" Function (see page 3-20).**

### 3.11.3 Tipdressing of Electrodes

With electrode tipdressing you can periodically restore the desired contact area during the electrode's life.

Therefore, after a certain wear, the electrodes must be treated in a tipdressing station for electrodes.

The timer requests tipdressing of electrodes via the "Tipdress prewarning" output signal (see page 6-22) or the "Tipdressing request".

The additional possibility to define up to 10 different tipdressing curves offers a perfect adaptability to different types of electrodes. A stepper curve determines the percentage with which the programmed command current should be increased automatically in dependence of the current electrode wear.

☞ **The resulting current changes can be monitored by means of the "Monitor Stepper" Function (see page 3-20).**

## Timer Functions

-  **The initial dressing function can be activated via parameter "tip-dressing of new electrodes".**  
**With Initial tipdressing activated, the timer requests tipdressing immediately after electrodes have been replaced.**  
**With freshly inserted electrodes this serves e.g.**
- to create a defined weld spot diameter
  - to create a defined contact angle
  - to eliminate a protective sheet.

### 3.11.4 Prewarning and End of Stepper

When the highest tolerable wear has been reached, new electrodes must be inserted.

Here, the output signals

- "Prewarning" (see page 6-23) and
  - "End of stepper" (see page 6-23) and
- are provided. They shall only be used if the electrode maintenance functions are activated (parameter "Stepper": ON).

### 3.11.5 Prewarning Table

The prewarning table offers you an overview with fast access to all important information and operations regarding electrodes with an activated electrode maintenance function:

- Weld timers to which the individual electrodes have been assigned.
- Current wear (in percent, numerical, and graphical).  
The graphic illustration is color coded. This way, upcoming prewarnings, tipdress requests, or the end of stepper can be easily recognized.
- Remaining parts that can still be welded with the relative electrode.
- Reset of one or more wear counters after the cap has been exchanged.

### 3.12 Tip Replacement (Tip Wear Monitoring )

This function is used to monitor the wear status of the tips. In this way, damaging of electrodes or bad tip jobs – which may be caused by worn tip cutters – can be avoided in advance by timely replacement of cutters.

To this end, an additional counter (value "Tip wear"; value range 0 to 99999) is provided in the timer in addition to the "normal" tipdressing counter (which is reset after replacement of electrodes). This tip wear counter is not reset after electrode replacement.

The timer increments the respective tip wear counter after each tipdressing of an electrode. If the tip wear counter has reached its programmable prewarning value (value "Prew. tip wear"), the "Prewarning tip replacement" output (see page 6-15) is set, and the message "Replace tip" is indicated via the GUI (BOS).

When the tip wear counter has reached its programmable end value (value "Max tip wear"), the timer sets the "Tip replacement" output (see page 6-16).

 **A tip's wear monitoring function can be deactivated by parameterizing the respective "Max. tip wear" with the value "0".**

Via the "Acknowledgement tip replacement" input signal (see page 6-13) or via BOS, a tip counter can be reset to the value "0" at any time.

### 3.13 Electrode Force

The indication which force the electrodes shall use to press the welded parts together (in kilonewton: kN) is part of any welding program.

Therefore, the timer generates – with an internal characteristic curve – for each programmed force value a corresponding output signal that can be used as an actuating variable for the electrode's force.

In order to output the force actuating variable,

- an analog signal to X2 (see page 5-7) **and**
- 8 serial output signals ("Prop. valve selection", see page 6-16) are provided.

The internal characteristic curve can be created either

- automatically by force scaling (please refer to chapter 3.14.1, page 3-31 ff).
- or**
- manually with the parameters "conversion factor" and "zero adjust".


## Timer Functions

"Conversion factor" (in kN/Volt):

With this factor, the timer calculates the output value of the actuating variable for the force. See illustration.

"Zero adjust" (in kN):

Moves the zero crossing of the characteristic curve. This way the characteristic curve can be adapted to the working zero of the actuator system in use. See illustration.



*Characteristic curve for output of force value*

- ☞ **In order to make the programmed force work on the electrodes, it is necessary to set the characteristic curve properly!**
- ☞ **During force scaling, the timer automatically calculates the necessary values for the parameters "conversion factor" and "zero adjust". After that, the parameters may not be altered manually!**

In addition to the possibility to program an electrode force that is constant for the entire welding process, the timer also offers the following functions:

- **Force profile:**  
It is possible to program 10 different force values for each welding program. These force values can then be activated at certain times within the welding process.
- **Force Stepper:**  
Depending on the selected stepper or tipdress curve, you can determine the percentage with which the programmed basic force value should be increased in dependence of the current electrode wear.

## 3.14 Scaling

 **Always scale the force first, then the current!**

### 3.14.1 Force scaling

With the function "force scaling", you adjust all components of the welding station that are part of the force build-up to their reference dynamometer (e.g. force transducer). This bears the following advantages:

- Presetting the gun force in kilonewton (kN)
- Exact reproducibility of logged force values (ISO 9000)
- Force values of all scaled stations can be compared to each other and transferred to other stations
- Comparable documentation.

 **Basically, the timer also works without force scaling. But you can only benefit from the above mentioned advantages after a force scaling procedure.**



#### CAUTION

**Risk of gun damage!**

**If you don't use force scaling, the timer cannot make a correct connection between the programmed force and the actuating variable for force that is to be output (necessary for controlling the force of the gun).**

**Therefore, the force that actually works on the gun can deviate immensely from the programmed force.**

**The consequences might be erroneous welds and even damages to the gun.**

**If you don't use the force scaling function, it is absolutely necessary to calculate empirically, after each gun exchange, the basic force value for each required electrode force – starting with the value "0".**

---

#### Prerequisites for force scaling:

- Proportional control valve, servo gun, or other suitable equipment that can convert the timer's actuating variable for force into a mechanical force at the gun.
- External reference dynamometer with appropriate measuring range.
- Coupled programming device with BOS software (for operation and input of measured values).

## Timer Functions

For force scaling, preset 2 different force actuating values in % (in relation to the highest value that can be output), use the reference dynamometer to measure the resulting forces between the electrodes, and enter the measured forces (in kN) into the timer.

The timer then calculates internally all data necessary for the adjustment.

When executing the force scaling function, please pay special attention to the following:

- ★ For the two actuating values used for force scaling, the following is applicable:  
If possible, the higher value shall generate the maximum force used for welding (upper end of the force working range).  
Both values should differ from each other by at least 20 %. The force required for electrode tipdressing is not to be assigned to the normal working range (because most of the times it is lower).  
If you do not know which value is to be entered for force scaling, use small values to execute sample scalings in order to see which forces will be generated at the gun. This way, you make sure not to overstress or damage the gun when force scaling. Then, slowly increase the preset value while executing further force scalings until the higher preset value generates the maximum force that you can use for welding.
  - ★ Please use for all comparable stations the same reference dynamometer.
  - ★ Execute for each gun in the welding station and after each gun exchange a scaling procedure.
  - ★ Verify an executed scaling by comparing the basic force values programmed in test welding programs with the actual values at the gun.  
Make sure that the test programs run **without current** and that people are safe during the measurements (possible danger caused by robot movements).
  - ★ Execute a new scaling if a component actively participating in force generation (weld timer, proportional control valve, gun...) has been exchanged.
-  **Force scaling changes the parameter "Conversion factor" and "Zero adjust" (in electrode setup, also refer to page 3-29). Therefore, after a force scaling procedure, the parameters may not be manually altered!**

### 3.14.2 Current Scaling

The function "Current scaling" serves to adapt the timer's entire measuring and control loop to your reference welding current measuring instrument. This bears the following advantages:

- Reproducible, presettable currents with a maximum error below  $\pm 2\%$  (in relation to the current value of the reference welding current measuring instrument)
- Exact reproducibility of logged current values (ISO 9000)
- Force values of all scaled stations can be compared to each other and transferred to other stations
- Comparable documentation.

 **The timer also works without current scaling. But you can only benefit from the above mentioned advantages after a force scaling procedure.**

#### **Prerequisites for force scaling:**

- A current sensor connected to X3 (see page 5-9).
- An external reference welding current measuring instrument with appropriate current sensor.
- Coupled programming device with BOS software (for operation and input of measured values).

 **Before executing a current scaling always execute a force scaling procedure (see page 3-31).**

For current scaling, preset 2 different currents in scale values, then use the reference welding current measuring instrument to measure the resulting currents in the secondary circuit, and enter the measured current values into the timer.

The timer then calculates internally all data necessary for the adjustment.

When executing the current scaling function, please pay special attention to the following:

- ★ The current sensor of the reference current measuring instrument must be installed correctly in the secondary circuit. This means:
  - always install it in the same place
  - install it vertically with regard to the current carrying conductor
  - the sensor cable faces away from the current carrying conductor.

## Timer Functions

- ★ For the two currents (in scale values) used for current scaling, the following is applicable:  
If possible, the higher value should lie at the upper end of the normal working range of your weld station.  
Both values should differ from each other by at least 20 scale values.
- ★ Please use for all comparable stations the same reference dynamometer.
- ★ Set your reference welding current measuring instrument to the right type of current ("AC" for PST, "DC" for PSI) and set the appropriate measuring range.
- ★ Programmed fadeout times and an activated trail current are also effective during current scaling!  
Therefore, prior to the scaling procedure, please check if the corresponding functions are available and correctly set in your measuring instrument.
- ★ Always scale without a welded part and with closed electrodes.
- ★ Execute for each gun in the welding station and after each gun exchange a scaling procedure.
- ★ Verify an executed scaling by doing a test weld comparing the current shown in the timer with the current shown in the reference welding current measuring instrument.
- ★ Execute a new scaling if a component actively participating in the control loop (weld timer, transformer, sensor...) has been exchanged.

### 3.15 Corrections

The timer's correction functions allow

- changes of current and
- pressure (electrode force).

This way you can quickly execute process-related adjustments and adaptations of the welding process without changing the originally programmed data. The corrections function as an addition to the programmed basic values.

You can activate both types of correction

- for a certain electrode/gun (= Corr. (E) and
- for individual programs or individual program sectors (= Corr. (P)).

 **When the current correction is changed, the reference current that is to be monitored will also be internally adjusted.**

 **The correction values can be limited in the basic settings. This limit can be set within the range of +/-20%.**

### 3.16 Weld Transformer Selection (PSI only)

In order for the PSI's power supply unit to function correctly, the timer must "know" certain technical data about the weld transformer in use. This requires the correct setting of a number of parameters in the "Weld transformer selection":

#### When using PSG weld transformers:

- "Type":  
Model of the PSG transformer according to name plate (e.g. "PSG 3100.00") and
- "Number":  
Number of parallel transformers.

With this data, the PSI knows the type of the diodes, the diode selection, and the highest permissible current for the welding station.

#### When using PSG weld transformers:

- "Type":  
Please switch to "Other transform.".
- "Number":  
Number of parallel transformers.

## Timer Functions

- "Secondary transformer current":  
Maximum secondary current of the transformer. The maximum welding current is limited to this value.
- "Transformer's transformation ratio":  
Transformation ratio primary/secondary. This parameter is necessary for converting primary and secondary current if for current measuring you use the current sensors integrated in the primary circuit (primary current regulation; used e.g. with transformers without integrated CC sensor).
- "Number of diodes":  
Number of diodes connected in parallel in the secondary circuit.
- "Type of diodes":  
Type of diodes used in the weld transformer.

**Diode monitoring:**

By means of the "Diode monitoring" parameter, the diode monitoring in the secondary circuit of the weld transformer can be activated and deactivated.

**CAUTION**

**Risk of destruction of the power supply unit or the weld transformer!**

**When diode monitoring is activated, the weld transformer's diodes are no longer monitored by the PSI. Under a high load this can lead to major damages to the welding station.**

**Therefore, always turn diode monitoring on!**

---

Technical data

## 4 Technical data

### 4.1 Integrated weld timer

Degree of protection	IP 20
Operating voltage	+24 V = ; +20 %, -15 % with max. +/-5 % ripple
Rated current at 24 V (without I/O module and without additional consumers at X5)	PSI: approx. 1.5 A PST: approx. 1.0 A
Starting current (without I/O module and without additional consumers at X5)	PSI: approx. 2.0 A for 10 ms PST: approx. 1.5 A for 10 ms
Operating temperature Temp. for storage/transportation Air pressure Humidity Climatic category	0 ... +55 degrees Celsius -25 ... +70 degrees Celsius 0 ... 2000 m above sea level Condensation not permissible. 3K3 to EN60721-3-3
Number of programs	max. 256; each program can be called up indi- vidually via the input signals "Program selection" or "Spot selection"
Programming on location	V24/RS232 interface, isolated. X1 connection: 9-pin D-Sub
Fieldbus for programming (option)	PROFIBUS-FMS or INTERBUS-PMS or Ethernet 10 MBit
Operating software (firmware)	Stored in Flash-Memory; can be loaded via "WinBlow" software package (optional)
Program memory	buffered RAM memory
Backup battery	Lithium battery Type AA 3.6 V to buffer RAM data and internal clock with MAINS OFF. Battery life approx. 2 years.
Pressure control for proportional valve	analog output (at X2): 0 to +10 V, max. 20 mA or 0 to 20 mA or 4 to 20 mA (at max. 500 ohms). Input feedback (to X2): logic 1: +16 V ... +30 V, 20 mA logic 0: -1 V ... +4 V

## Technical data

Main switch trigger MST (only with PST)	Relay contacts (to X8). Resilience: 24 VDC, max. 6 A 42 V~, max. 1 A
Electrodes	max. 5 (no. 0 to no. 4)

## 4.2 I/O Module "DEV-NET"

### Function:

Connection of the timer's I/O to the higher-level PLC or the robot

- via DeviceNet with bus copper cable (serial I/Os) and
- via discrete 24 V signals at X11 and X12 (parallel I/Os).

Operating voltage (at X10)	+24 V= +20 %, -15 % with max. +/-5 % ripple
Current input	max. 2 A depending on the wiring of the signal in-/outputs
Power loss	0.5 VA per active input 2.4 VA per active output
Signal input field via DeviceNet Signal output field via DeviceNet	9 byte, max. 72 signals (0 to 71) 9 byte, max. 72 signals (0 to 71)
Signal inputs (X12) Signal outputs (X11)	logic 1: +16 V ... +30 V, 20 mA logic 0: -1 V ... +4 V +24 V, max. 0.1 A, short circuit-proof


Electrical Connection

## 5 Electrical Connection

### 5.1 Interference Suppression

Interferences (RF noise) are caused by transient peaks and can be spread into the timer either directly or by coupling via connecting lines. For this reason, measures for interference suppression are necessary.

- ★ Eliminate interferences already at their source. If this is not possible, install the interference suppression devices as close to the interference source as possible.
- ★ Make sure that all components that contain inductivities or switch elements are properly cleared.
- ★ Install interference suppression devices always in such a way that they cannot break since machines are often subject to strong vibrations.



*Examples for interference suppression*

 **The following table is only an example. The dimensions of the necessary modules depend on the actual load ratios.**

	Resistor	Capacitor	Diode
24 V <sub>DC</sub>	-	-	1 N 5060/ZL 12
48 V <sub>DC</sub>	-	-	1 N 5060/ZL 22
110 V <sub>AC</sub>	220 ohms / 1 W	0.5 uF 400/600 V	
220 V <sub>AC</sub>	220 ohms / 5 W	0.1 uF 500 V	
440 V <sub>AC</sub>	220 ohms / 5 W	0.1 uF 1000 V	

## Electrical Connection

## 5.2 Integrated weld timer


☞ For technical data, please refer to chapter 4.1, on page 4-1.

### 5.2.1 Output of the Internal 24 V<sub>DC</sub> Voltage Source (X4)

Connection:	at X4; plug-in terminal, spacing 3.5 mm, 14-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	(From the voltage source to the consumer) max. 10 m with 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

At X4, a 24 V<sub>DC</sub> supply voltage that the power supply unit derives from the mains voltage is at your disposal.

☞ **The supply through the internal 24 V<sub>DC</sub> voltage source and therefore the functionality of all devices fed from this source is guaranteed only if mains voltage is applied at the mains input of the power supply unit!**



*Internally generated 24 V<sub>DC</sub> power supply*

★ Please consider the following facts when using the internal 24 V<sub>DC</sub> voltage source:

- max. current load: 2.5 A.
- When supplying the timer logics:  
If you switch off the mains voltage at the mains input of the power supply unit, you automatically switch off the timer as well. In this state,
  - neither programming, diagnosis, or visualization via the timer
  - communication between timer and PLC/robot is not possible anymore.
- When supplying the I/O module:  
If you switch off the mains voltage at the mains input of the power supply unit, you automatically switch off the I/O module as well. In this state,
  - communication between timer and PLC/robot is not possible anymore.


## Electrical Connection

☞ **If the above describe facts are not compatible with your application, the 24 V<sub>DC</sub> supply of timer or I/O module must be provided by external power supply units.**

## 5.2.2 Supply of the Timer Logics (X4)

Connection:	at X4; plug-in terminal, spacing 3.5 mm, 14-pin, max. 1.5 mm. Mating connector included in shipment.
Cable length:	(From the voltage source to the consumer) max. 10 m with 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

The timer logics must be supplied with 24 V<sub>DC</sub>.



*Logics supply input of the timer*

The remaining wiring of X4 determines which voltage source supplies the timer. You can select

- either the internal voltage source (refer to page 5-2) and
- an external power supply unit.

To do so, you only have to set/remove some jumpers at X4.

☞ **For more information about the interconnections of X4, please refer to chapter 5.2.4 on page 5-4 ff.**

While a supply through the internal voltage source is preferred in standalone installations (e.g. suspended welding station; additional 24 V<sub>DC</sub> power supply units are not necessary), a supply via external power supply units is mainly used in networked timers (timer can be programmed even if the welding network has been switched off e.g. via the line PC).

- ★ If you use external voltage sources, please make sure that they are specified as "safely separated" according to the Low-Voltage Directive (72/23/EEC, 93/68/EEC and 93/44/EEC)!


## Electrical Connection

### 5.2.3 Supply of External Devices (X5)

Connection:	at X5; plug-in terminal, spacing 3.5 mm, 2-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	Depends on the wiring at X4. See description below.
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

X5 is at your disposal for the 24 V<sub>DC</sub> supply of an external device (e.g. force sensor).

The maximum current load/cable length at X5 depends on the voltage source in use and the entire length of the cable between source and external consumer. The maximum current load at X5 must not exceed 0.5 A.



Connection of external devices to X5

- ★ Make sure not to exceed the limit values specified for current load (source, connections) and cable lengths!
- ☞ **The remaining wiring of X4 determines which voltage source supplies X5.**  
You can use either the internal voltage source (see page 5-2) or an external power supply unit. To do so, you only have to set/remove some jumpers at X4. For more information about the interconnections of X4, please refer to chapter 5.2.4 on page 5-4 ff.

### 5.2.4 24 V<sub>DC</sub> Voltage Distribution (X4)

Connection:	at X4; plug-in terminal, spacing 3.5 mm, 14-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	(From the voltage source to the consumer) max. 10 m with 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>

## Electrical Connection

Type of cable: Unshielded, VDE 0281, 0812  
(e.g.: Ölflex)

The internal circuit of X4 facilitates the wiring of the 24 V<sub>DC</sub> supply branches for the timer and the I/O module substantially. By plugging or removing certain jumpers, you can realize different supply variations without altering the remaining wirings in the switch cabinet.

To do so, connect the relevant voltage source to X4/6 (24 V<sub>DC</sub>) and X4/7 (0 V).

Below you find descriptions of some possibilities. In the following, please find the illustrations representing the appropriate wiring.

Which kind of wiring is suitable for you, depends on the requirements of your application.

1. Timer **and** I/O module are fed by an **internal** 24 V<sub>DC</sub> voltage source.

Application: Used preferably in standalone installations.

Advantage: Separate power supply units are not necessary.

Disadvantage: 24 V<sub>DC</sub> will only be generated if the mains voltage is present at the power supply's mains input.

2. The I/O module is fed by an **internal** 24 V<sub>DC</sub> voltage source, the timer is fed by an **external** power supply unit.

Application: Used in networked installations.

Advantage: Programming, diagnosis, and visualization are still possible even after the mains voltage at the power supply unit's mains input has been switched off.

Electrical isolation between timer and I/O module with discrete in-/outputs (parallel I/O) is possible.

Disadvantage: If you switch off the mains voltage at the mains input of the power supply unit, I/O communication between timer and PLC/robot is not possible anymore.

3. Timer **and** I/O module are both supplied by a **mutual external** 24V power supply unit.

Application: Used preferably in networked installations.

Advantage: I/O communication between timer and PLC/robot, programming, diagnosis, and visualization are still possible even after the mains voltage at the power supply unit's mains input has been switched off.

Disadvantage: Electrical isolation between timer and I/O module with discrete in-/outputs (parallel I/O) is not possible.

4. Timer **and** I/O module are both supplied by **separate external** 24V power supply units.


Application: Used in networked installations.

Advantage: I/O communication between timer and PLC/robot, programming, diagnosis, and visualization are still possible even after the mains voltage at the power supply unit's mains input has been switched off.

Electrical isolation between timer and I/O module with discrete in-/outputs (parallel I/O) is possible.

Disadvantage: 2 external power supply units are necessary.

Electrical Connection



Examples for wiring

## Electrical Connection

**5.2.5 Pressure Control and Feedback (X2)**

Connection:	at X2; plug-in terminal, spacing 3.5 mm, 5-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	max. 50 m at 0.5 mm <sup>2</sup> max. 100 m with 0,75 mm <sup>2</sup>
Type of cable:	shielded (e.g.: NFL 13, Metrofunk; LiYCY)

An analog output signal that can be used for controlling a proportional control valve is at your disposal at X2 Pin 1. The type of the output signal can be alternatively programmed as

- a voltage signal (0 to +10 V, max. 20 mA),
- a current signal 0 to 20 mA or
- a current signal 4 to 20 mA.

The proportional control valve converts the pending signal into a pressure which will be applied to the gun cylinder. According to the mechanics of the gun, this will result in the force available at the electrodes (see also page 3–29).

 **For pressure control, 8 serial output signals are available in addition to the output signal at X2 ("Prop. Valve Selection", by DEV-NET; see page 6–16).**

 **The output signal at X2 will be output immediately after the selection of a welding program and not only upon its start!**

In order to signal to the timer that the gun is closed or that the command force has been reached, you use

- the input terminal 4 at X2.

The programmed squeeze time (SQZ) starts under the following conditions only:

- High level at input X2/4 (in relation to 0V at X2/2)  
(for required voltage, please refer to chapter 4.1, on page 4–1).


If this condition is missing, the welding program will be selected and started (and a possibly programmed 1.SQZ will begin), but the further processes (schedule) will be delayed until this one condition is met.

Which sensors and input signals are used for feedback depends on the respective application. The entire pressure control and feedback e.g. can also be handled via PLC program (if proportional control valve and feedback are not connected to the timer itself but to the PLC or the robot). In addition, applications without feedback or proportional control valve are possible as well.


The following illustrations represent several connection possibilities.

Electrical Connection

- ★ Make sure that in installations without feedback signal, the welded part has been perfectly pressed together before the weld time starts! In order to do so, you have to program sufficiently long squeeze times. Insufficient squeeze times lead to a large amount of welding splashes! This might lead to damage to the electrodes and work pieces.




Connection of a proportional control valve with feedback



Connection of a proportional control valve without feedback

- ☞ **The connection "without feedback" is applicable if**
  - the proportional valve does not return a feedback signal, or
  - the feedback signal is connected to the PLC/robot.

## Electrical Connection



Wiring without proportional control valve

- ☞ **The connection "wiring without proportional control valve" is applicable if**
- you don't use a proportional control valve or
  - the proportional control valve and the feedback signal are connected to the PLC/robot.

- ★ If pressure control and feedback are completely handled by the PLC program, the PLC/robot must make sure that the programmed weld time will be started only if the gun/electrodes are in proper condition. To do so, two solutions are possible:

1. The PLC informs the weld timer via input X2/4.  
With this solution, the welding program will be started, but the SQZ starts running only when a "high" level is available at the input mentioned.
2. The PLC starts the welding program only if the proper condition of the gun/electrodes can be guaranteed.  
With this solution, permanently apply high-level to input X2/4 and always program the lowest SQZ in all welding programs (PST: 1 line cycle; PSI: 16 ms).

## 5.2.6 KSR Sensor (X3)

Connection:	at X3; plug-in terminal, spacing 3.5 mm, 8-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	max. 100 m (with recommended type of cable)
Type of cable:	shielded, core cross section min. 0.75 mm <sup>2</sup> , (e.g.: 2 x 2 x 0.75 mm <sup>2</sup> LiYCY, Bosch order no.: 1070 913 494)

## Electrical Connection

The timers are provided with an integrated Constant Current Regulation (KSR). The timer controls the current flow in the secondary circuit so that the programmed command current can actually be reached.


This way, it is possible to compensate process- and handling-related fluctuations of the contact resistance between electrode - workpiece - electrode.

A sensor which indicates the current flow in the primary and secondary circuit of the welding transformer is required for the regulation.

A current sensor installed in the secondary circuit can be connected via the toroid input (X3; terminal 1 and 2).

**PSI devices additionally have an integrated current sensor for the primary circuit of the welding transformer. This allows you to choose between secondary and primary measurement by means of the software (BOS).**

**In case of weld times > 1 s or for temporary bridging over in the presence of failure of the sensor in the secondary circuit, change to primary measurement.**



*Connection of the KSR sensor on the secondary side*

In order to ensure the proper operation of the sensor, please comply with the following:

- ★ Install the sensor in such a way that it is safe from damage caused by the work piece and from welding splashes. Choose places with the highest possible distance to the busbars or high current cables. This reduces the influence of externally originating magnetic induction. Please comply with the above mentioned cable specifications. Never use magnetizable metal parts for fastening, but preferably copper or brass.
- ★ Make sure that the currentcarrying conductor is lead straight and centrally through the sensor. The voltage induced in the sensor (and therefore the measuring variable) has reached its maximum when the conductor runs vertically to the spanned sensor plane.

## Electrical Connection

- ★ If the sensor is used in movable equipment (e.g. robots), certain parts of the cables are subject to very strong mechanical stress (e.g. trailing chain).  
In such cases, please use appropriate cables and set the connecting lines in such a way that in case of an error, they can be exchanged quickly and easily.
- ★ Connect the cable shield only at the side where the timer is located!
- ★ Adjust the timer's entire control loop regularly in order to avoid measuring faults (current scaling). For this purpose, an external reference welding current measuring instrument is required.

**Measuring circuit test:**

During the SQZ, the timer checks, by measuring the ohmic resistance, if the connected measurement circuit is faultless or not. This way, problems in the area sensor cable plug can be detected.

The following test criteria apply:

Measured ohmic resistance	Result
< 7 ohms	short circuit of measuring circuit
12 to 950 ohms	measuring circuit ok
> 1100 ohms	measuring circuit open

- ☞ **Measuring values in between lead to an ambiguously assessable result.**

In case of an error, the timer interrupts the welding process and deletes the output signal "Ready".


**5.2.7 Main switch trigger (X8) (only with PST)**

Connection:	at X8; plug-in terminal, spacing 3.5 mm, 3-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	max. 10 m at 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

## Electrical Connection

The function "Current passed without command" checks whether a voltage not initiated by the timer has been applied between the primary circuit terminals of the welding transformer (signal: Current passed without command). If this is the case, the internal floating contact at X8 (change-over switch) will short-circuit the terminals 2 and 3.

The use of main switches with a suitable functionality results in automatic triggering of the main switch and thus to deactivation of the power supply if suitable wiring of X8 (break contact/make contact) has been provided.




*Connection terminals for main switch trigger*

## Electrical Connection

## 5.2.8 Fan connection (X4)

Connection:	at X4; plug-in terminal, spacing 3.5 mm, 14-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	max. 10 m at 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

✎ **Not all timers can provide a temperature-controlled 24 V<sub>DC</sub> connection of an external forced ventilation (max. 2 A). See wiring diagram of the corresponding timer.**  
**Forced ventilation modules are used for example in various types of welding unit housing,**




Connection of an external fan module

## 5.2.9 Programming unit (X1)

Connection:	at X1; D-sub, 9-pin, at the cable via socket
Cable length:	max. 20 m (with recommended type of cable)
Type of cable:	shielded, core cross section min. 0.2 mm <sup>2</sup> , Capacity max. 2.5 nF (e.g.: 3 x 2 x 0.2 mm <sup>2</sup> LifYCY, Metrofunk)

For connecting the programming unit (PC, Laptop), please use the RS232 interface X1.



Transmission rate:	19200 bits/s
Parameter:	8E1 (8 data bits, even parity, 1 stop bit)
Transmission:	PS5000 block protocol with CRC16

## Electrical Connection

### 5.3 I/O Module "DEV-NET"

The complete communication between timer and higher-level PLC or robot is primarily handled via DeviceNet (copper cable).

In addition, there are discrete 24 V<sub>DC</sub> signals available, which can be used via PLC, robot or control panel.

Therefore, the I/O module provides

- 8 inputs (24 V<sub>DC</sub>, at X12)
- 8 outputs (24 V<sub>DC</sub>, at X11)
- 9 byte input field (DeviceNet connection)
- 9 byte output field (DeviceNet connection).

#### 5.3.1 Power Supply (X10)

Connection:	at X10; plug-in terminal, spacing 3.5 mm, 4-pin, max. 1.5 mm <sup>2</sup> . Mating connector included in shipment.
Cable length:	(From the voltage source to the consumer) max. 10 m with 0.75 mm <sup>2</sup> max. 75 m with 1.5 mm <sup>2</sup>
Type of cable:	Unshielded, VDE 0281, 0812 (e.g.: Ölflex)

 **For further technical data, please refer to chapter 4.2 on page 4-2.**

**Two types of connection** are possible:



1. Connection of the I/O module supply to X4 of the timer or
2. direct connection of the I/O module supply to a separate 24 V<sub>DC</sub> power supply unit.

 **If you connect the I/O module to the timer's X4 (1. type of connection), you can use either the internal voltage supply (see page 5-2) or an external power supply unit. To do so, you only have to set/remove some jumpers at X4. For more information about the interconnections of X4, please refer to chapter 5.2.4 on page 5-4 ff.**


- ★ Make sure to use only such external voltage sources that are specified as "safely separated" according to the Low-Voltage Directive (72/23/EEC, 93/68/EEC and 93/44/EEC)!
- ★ If an electrical isolation between I/O and timer is necessary, the timer and the I/O module must be operated via separate 24 V<sub>DC</sub> voltage supply units!
- ★ Please make sure that the correct function of the **stop circuit** (see illustrations below) is guaranteed in every connection type!  
In dangerous situations at the welding station or in case of intended switch-off of the weld timer, the in- and outputs of the I/O module are to be switched to low level. To do so, an external monitoring device must open the floating contact which then interrupts the power supply at X10.

## Electrical Connection

In case of an open stop circuit, the timer sends the following message: "Stop circuit open / no 24 V". This message is automatically reset, i.e. it disappears automatically when the stop circuit is closed.



Connection of the I/O module supply to X4 of the timer



Direct connection of the I/O module supply to a separated 24 V<sub>DC</sub> power supply unit.


- ★ Use terminal 3 at X10 as a 24 V source for triggering the inputs at X12. Use terminal 4 at X10 as a 0 V reference potential at X11.
- ★ Because of the internal jumper at X10, the incoming supply voltage can be transferred to further devices. Make sure, though, not to exceed the limit values specified for current load (voltage source, connections) and cable lengths!

Electrical Connection

### 5.3.2 DeviceNet Connection

In order to integrate the timer in a DeviceNet bus system, please use X13.

Cable length: according to DeviceNet specification  
 Type of cable: copper, shielded, according to DeviceNet specification



Example: DeviceNet connection of the last 3 weld timers at the bus

**For more information on which I/O signals are exchanged between the weld timer and the DevNet host, please refer to chapter 5.3.3.**

**Setting the DeviceNet address:**

via NA switch. Address (MAC ID) according to DeviceNet specification.

**Setting the DeviceNet baud rate:**

via DR switch, according to DeviceNet specification.


### 5.3.3 Signal outputs and inputs

Connection X11, X12: Plug-in terminal, spacing 3.5 mm, max. 1.5 mm<sup>2</sup>.  
 Mating connector included in shipment.

Cable length: max. 100 m at 0.5 mm<sup>2</sup>  
 Type of cable: unshielded, VDE 0281, 0812 (e.g.: Ölflex)

Electrical Connection

☞ For further technical data, please refer to chapter 4.2 on page 4-2. For information regarding the functionality of all signals, please refer to chapter 6.



Assignment of all signal in- and outputs

Electrical Connection

Input field, byte 0 and 1			Output field, byte 0 and 1		
Bit	Signal name	Description Refer to page	Bit	Signal name	Description Refer to page
0	TIPS HAVE BEEN DRESSED	6-2	0	WELD COMPLETE (WC)	6-18
1	WELD ON EXTERNAL	6-5	1	WITH IGNITION	6-21
2	RESET FAULT	6-6	2	WITHOUT MONITORING FUNCTION	6-21
3	RESET FAULT WITH SPOT REPEAT	6-7	3	WITHOUT REGUL. AND WITHOUT MON. FUNC.	6-22
4	RESET FAULT WITH SPOT REPEAT	6-8	4	WELDING FAULTS	6-20
5	reserved		5	CONTROL READY	6-19
6	reserved		6	AUTOMATIC PROGRAM SELECTION ACTIVE	6-22
7	reserved		7	reserved	
8	ACKNOWLEDGEM. 'TIPS HAVE BEEN DRESSED'	6-9	8	TIPDRESS PREWARNING ELECTRODE 1	6-22
9	ACKNOWLEDGEM. 'TIPS HAVE BEEN DRESSED'	6-9	9	TIPDRESS PREWARNING ELECTRODE 2	6-22
10	ACKNOWLEDGEM. 'TIPS HAVE BEEN DRESSED'	6-9	10	TIPDRESS PREWARNING ELECTRODE 3	6-22
11	ACKNOWLEDGEM. 'TIPS HAVE BEEN DRESSED'	6-9	11	TIPDRESS PREWARNING ELECTRODE 4	6-22
12	ACKNOWLEDGM. 'ELEC. HAVE BEEN REPL.' 1	6-11	12	TIPDRESSING REQUEST ELECTRODE 1	6-22
13	ACKNOWLEDGM. 'ELEC. HAVE BEEN REPL.' 2	6-11	13	TIPDRESSING REQUEST ELECTRODE 2	6-22
14	ACKNOWLEDGM. 'ELEC. HAVE BEEN REPL.' 3	6-11	14	TIPDRESSING REQUEST ELECTRODE 3	6-22
15	ACKNOWLEDGM. 'ELEC. HAVE BEEN REPL.' 4	6-11	15	TIPDRESSING REQUEST ELECTRODE 4	6-22

Assignment of the input and output field for Device-Net coupling (byte 0 and 1)

Input field, byte 2 and 3			Output field, byte 2 and 3		
Bit	Note		Bit	Note	
16	ACKNOWLEDGEMENT 'TIP REPLACEMENT' 1	6-13	16	PREWARNING ELECTRODE 1	6-23
17	ACKNOWLEDGEMENT 'TIP REPLACEMENT' 2	6-13	17	PREWARNING ELECTRODE 2	6-23
18	ACKNOWLEDGEMENT 'TIP REPLACEMENT' 3	6-13	18	PREWARNING ELECTRODE 3	6-23
19	ACKNOWLEDGEMENT 'TIP REPLACEMENT' 4	6-13	19	PREWARNING ELECTRODE 4	6-23
20	reserved		20	END OF STEPPER ELECTRODE 1	6-23
21	reserved		21	END OF STEPPER ELECTRODE 2	6-23
22	reserved		22	END OF STEPPER ELECTRODE 3	6-23
23	reserved		23	END OF STEPPER ELECTRODE 4	6-23
24	reserved		24	PREWARNING TIP REPLACEMENT 1	6-15
25	reserved		25	PREWARNING TIP REPLACEMENT 2	6-15
26	reserved		26	PREWARNING TIP REPLACEMENT 3	6-15
27	reserved		27	PREWARNING TIP REPLACEMENT 4	6-15
28	reserved		28	TIP REPLACEMENT 1	6-16
29	reserved		29	TIP REPLACEMENT 2	6-16
30	reserved		30	TIP REPLACEMENT 3	6-16
31	reserved		31	TIP REPLACEMENT 4	6-16

Assignment of the input and output field for Device-Net coupling (byte 2 and 3)

## Electrical Connection

Input field, byte 4 and 5			Output field, byte 4 and 5		
Bit	Signal name	Description Refer to page	Bit	Signal name	Description Refer to page
32	SPOT SELECTION 01	6-3	32	PROP. VALVE SELECTION 01	6-16
33	SPOT SELECTION 02	6-3	33	PROP. VALVE SELECTION 02	6-16
34	SPOT SELECTION 04	6-3	34	PROP. VALVE SELECTION 04	6-16
35	SPOT SELECTION 08	6-3	35	PROP. VALVE SELECTION 08	6-16
36	SPOT SELECTION 16	6-3	36	PROP. VALVE SELECTION 16	6-16
37	SPOT SELECTION 32	6-3	37	PROP. VALVE SELECTION 32	6-16
38	SPOT SELECTION 64	6-3	38	PROP. VALVE SELECTION 64	6-16
39	SPOT SELECTION 128	6-3	39	PROP. VALVE SELECTION 128	6-16
40	SPOT SELECTION 256	6-3	40	SHEET THICKNESS 01	6-17
41	SPOT SELECTION 512	6-3	41	SHEET THICKNESS 02	6-17
42	SPOT SELECTION 1024	6-3	42	SHEET THICKNESS 04	6-17
43	SPOT SELECTION 2048	6-3	43	SHEET THICKNESS 08	6-17
44	SPOT SELECTION 4096	6-3	44	SHEET THICKNESS 16	6-17
45	SPOT SELECTION 8192	6-3	45	SHEET THICKNESS 32	6-17
46	SPOT SELECTION 16384	6-3	46	SHEET THICKNESS 64	6-17
47	SPOT SELECTION 32768	6-3	47	SHEET THICKNESS 128	6-17

Assignment of the input and output field for Device-Net coupling (byte 4 and 5)

Input field, byte 6 and 7			Output field, byte 6 and 7		
Bit	Signal name	Description Refer to page	Bit	Signal name	Description Refer to page
48	SPOT SELECTION 65536	6-3	48	SHEET THICKNESS TOLERANCE 01	6-17
49	SPOT SELECTION 131072	6-3	49	SHEET THICKNESS TOLERANCE 02	6-17
50	SPOT SELECTION 262144	6-3	50	SHEET THICKNESS TOLERANCE 04	6-17
51	SPOT SELECTION 524288	6-3	51	SHEET THICKNESS TOLERANCE 08	6-17
52	reserved		52	SHEET THICKNESS TOLERANCE 16	6-17
53	reserved		53	SHEET THICKNESS TOLERANCE 32	6-17
54	reserved		54	SHEET THICKNESS TOLERANCE 64	6-17
55	reserved		55	SHEET THICKNESS TOLERANCE 128	6-17
56	SPOT SELECTION READY	6-4	56	SPOT SELECTION TAKEN OVER	6-23
57	reserved		57	STATUS 01	6-24
58	reserved		58	STATUS 02	6-24
59	reserved		59	STATUS 04	6-24
60	reserved		60	STATUS 08	6-24
61	reserved		61	STATUS 16	6-24
62	reserved		62	STATUS 32	6-24
63	reserved		63	STATUS 64	6-24

Assignment of the input and output field for Device-Net coupling (byte 6 and 7)

Input field, byte 8			Output field, byte 8		
Bit	Signal name	Description Refer to page	Bit	Signal name	Description Refer to page
64	reserved		64	STATUS 128	6-24
65	reserved		65	reserved	
66	reserved		66	reserved	
67	reserved		67	reserved	
68	reserved		68	reserved	
69	reserved		69	reserved	
70	reserved		70	reserved	
71	reserved		71	reserved	

Assignment of the input and output field for Device-Net coupling (byte 8)

## Electrical Connection

Notes:

## 6 I/O Signal Descriptions

This chapter contains the descriptions of all I/O signals regarding their importance for the timer. Signal names are always put in quotation marks ("Signal name").

 **For information regarding the assignment of all in-/output signals of the "DEV-NET" I/O module, please refer to chapter 5.3.3 from page 5-16.**

### 6.1 Input Signals

#### 6.1.1 Alphabetical Overview

Signal name	Page
RESET FAULT	6-6
RESET FAULT WITH SPOT REPEAT	6-8
RESET FAULT WITH WC	6-7
SPOT SELECTION	6-3
AUTOMATIC PROGRAM SELECTION ACTIVE	6-4
SPOT SELECTION READY	6-4
ACKNOWLEDGEMENT 'TIPS HAVE BEEN DRESSED'	6-11
ACKNOWLEDGEMENT 'ELECTRODES HAVE BEEN REPLACED'	6-11
ACKNOWLEDGEMENT CUTTER CHANGE	6-13
START	6-2
WELD ON EXTERNAL	6-5

## I/O Signal Descriptions

## 6.1.2 Start

A positive edge at the input triggers the acceptance of the currently selected welding program (for more information regarding program selection, see page 6-3) if the timer is in "Ready" (see page 6-19).

Schedule:

1. The welding program starts.  
If programmed, the 1.SQZ starts running.
2. SQZ starts.  
Up to the end of the SQZ, the welding schedule can be aborted by resetting "Start".

☞ **Within the SQZ, the timer checks, by measuring the ohmic resistance, whether the connected measurement circuit is faultless or not.**


**In case of an error (refer to page 5-11), the timer interrupts the welding program and deletes the output signal "Control ready".**

3. If "Start" continues to be high after the end of the SQZ, Interlock starts in single mode. While in Interlock, the 1., 2., and 3.WLD run even after resetting "Start".  
After resetting "Start" in seam mode, only a current cycle that has already begun will be finished.

☞ **Even with interlock active, welding times can be aborted by opening the stop circuit (see page 5-15).**


☞ **Whether the weld times are executed with or without welding current depends on the input signal "Weld on external" (refer to page 6-5).**

4. HLD starts running.
5. The output "Weld complete" (refer to page 6-18) acknowledges the weld schedule.



*Interlock in single mode*

I/O Signal Descriptions




Reset of "Start" during 2.WLD in seam mode

### 6.1.3 Selection of program / spot

In dependence on the input signal "Automatic program selection active" (see page 6-4), the input signals are used to select the desired

- welding program (0 to 255), or
- welding spot (256 through 1048576).

To do so, the binary coded program/spot number will be applied to the inputs. Then, use the input signal "Spot selection ready" (see page 6-4) to instruct the timer to interpret the program/spot selection input.



Binary coded selection of a spot (of an electrode) via input signals "Spot selection x"

**When you select a spot then you always select the corresponding program as well.**

## I/O Signal Descriptions

- ☞ **Immediately after selection of a welding program, the control outputs to X2 an output voltage corresponding to the programmed setpoint pressure (see page 5-7). Additionally, the outputs "Prop. valve selection" (see page 6-16) signal the setpoint pressure via the DevNet interface.**
  
- ☞ **The function "Start simulation" within the user interface (BOS) always refers to program numbers!**

### 6.1.4 Automatic program selection active

The input signal defines how the timer interprets the bit pattern at the inputs "Spot selection x" (see page 6-3):

- High-level at input: Interpretation as program number.  
When the signal "Spot selection ready" (see Chapter 6.1.5) is set, any program numbers greater than 255 result in the error message "Faulty program selection".
- Low-level at input: Interpretation as program number.  
When the signal "Spot selection ready" (see Chapter 6.1.5) is set, any program numbers smaller than 256 result in the error message "Faulty spot number".

- ☞ **The status of the input signal is mirrored at the output signal "Automatic program selection active (see page 6-22).**

### 6.1.5 Spot selection ready

In connection with the output signal "Spot selection taken over" (see page 6-23), the input signal is used to perform the handshake with PLC/robots (e.g. when servotongs are used).

Handshake schedule:

1. The PLC/robot sets the "Spot selection ready" input as soon as the desired spot number is pending in the "Spot selection" inputs (see page 6-3).
2. The timer reacts with setting the "Program selection taken over" output signal once it has selected the spot (and the corresponding program).  
Simultaneously, the timer outputs the programmed command force of the electrodes, the sheet thickness (see page 6-17) and the sheet thickness tolerance (see page 6-17).
3. Now, PLC/robot must reset the input signal "Spot selection ready".
4. In return, the control resets the output signal "Spot selection taken over".

## I/O Signal Descriptions

## 6.1.6 Ignition on, external

Sometimes it is necessary to execute a welding program without weld current (e.g. within the scope of a clock time optimization at the welding line or for other settings/tests).

Therefore, an external device (robot, PLC, keylock switch at the control panel) can determine via this input signal.

1. whether the timer should execute all welding programs without current as a rule or
2. whether the timer itself, based on the parameterization, has an influence on this decision (with or without current).

Regarding point 1.:

If "Weld on external" **is not set**, all welding programs in the timer – independent from the rest of the timer's parameterization – will be executed without current. The power supply unit will not be triggered in this case.

Regarding point 2.:

If "Weld on external" **is set**, the reaction depends on the following parameters:

- Weld on internal (globally affects all programs in the timer) and
- program-related weld (is part of each welding program and is effective in the corresponding program only).

The execution of a welding program **with current** is possible only if

- "Weld On External" is set and
- Weld on, internal
- the program-related weld (firing) has been switched on.

This corresponds to an AND operation of all 3 mentioned conditions.

 **For feedback of this AND operation to an external device, please use the output signal "Weld / No weld" (see page 6-21).**

## I/O Signal Descriptions

## 6.1.7 Reset fault

If an error occurs, the timer goes into "Block".  
In this state,

- it is not possible to start a welding process (schedule)
- the LED READY at the timer's front goes off (see page 2-8)
- the output signal "Control Ready" will be reset (refer to page 6-19).

 **Error and status messages are listed in the "Error list PS5000/PS6000" (No.: 1070 087 000).**

While the timer automatically deletes "self-resetting" errors after the cause of the error has been eliminated, "not self-resetting" errors require a "reset fault" after the elimination.

This operation can be executed either via

- Software (BOS),
- the reset button at the timer's front (see page 2-8) or
- a positive edge of the "Fault reset" input signal.

★ Please note that after "Reset fault", the timer only restores the "Ready" state. In "Ready" the following is applicable:

- it is possible to start a new welding process
- the LED READY at the timer's front is lit
- and the output signal "Control ready" is set.

 **The timer does not execute any other actions!**  
**If the error occurs during a welding process, the gun might still be closed and the robot e.g. remains on the current welding position.**

Via the input signals "Reset fault with WC" (see page 6-7) and "Reset fault with spot repeat" (see page 6-8), other operations can be initiated in addition to "Reset fault". Please refer to the indicated cross references.

## I/O Signal Descriptions

## 6.1.8 Error Reset with WC

☞ **For basic information, please refer to page 6-6!**

A positive signal edge leads to

1. "Reset fault" and subsequent
2. setting of the signal "Weld complete" if the input signal "Start" is still pending.

**DANGER**

**Hazardous machine movements may be the result!**

**The signal "Weld complete" initiates the robot's positioning to the next weld spot.**

**Therefore, make sure to avoid dangerous situations at the welding station caused by "Reset fault with WC"!**

---

☞ **"Reset error with WC" can also be triggered via the GUI (BOS).**

"Reset error with WC" is used

- in connection with robots and
- in connection with all errors except "Current too low" and "Current too low for a series of welds".

☞ **In connection with errors except "Current too low" and "Current too low for a series of welds", please note the signal "Reset fault with spot repeat". Refer to page 6-8.**

If an error occurs while a part is being welded, the robot usually remains at the welding position with the gun closed. Via "Reset Fault with WC", it is now possible

- to continue the process at the next weld spot.

**CAUTION**

**The current spot weld is erroneous!**

**Please check the part!**

---

## I/O Signal Descriptions

## 6.1.9 Error Reset with Spot Repeat / WC

☞ For basic information, please refer to page 6-6!

A positive signal edge leads to

1. "Reset fault" and subsequent
2. repetition of the welding program schedule provided that the input signal "Start" is still pending.  
If the repetition is completed without another error, the signal "Weld complete" will be set.

**DANGER**

**Hazardous machine movements may be the result!**

**The signal "Weld complete" initiates the robot's positioning to the next weld spot.**

**Therefore, make sure to avoid dangerous situations at the welding station caused by "Reset fault with spot repeat / WC"!**

---

☞ "Reset error with WC" can also be triggered via the GUI (BOS).

"Reset error with WC" is used

- in connection with robots and
- in connection with the errors "Current too low" and "Current too low for a series of welds".

☞ In connection with other errors, please note the signal "Reset fault with WC". Refer to page 6-7.

If the error "Current too low" or "Current too low for a series of welds" occurs while a part is being welded, the robot usually remains at the welding position with the gun closed. Via "Reset Fault with WC", it is now possible

- to repeat the current, erroneous spot weld.

If, after that, another error occurs, please use "Reset error with WC".

## I/O Signal Descriptions

## 6.1.10 Acknowledgement 'Tips Have Been Dressed' x

The timer informs the robot the "Tipdress prewarning" (see page 6-22) that "shortly" a specific tip will need dressing (see page 3-27).

 **The time for outputting the signal "Tipdress prewarning" is parameterizable (BOS).**

When the robot recognizes the "Tipdress prewarning", it must move the relevant electrode to the tipdress station – at the latest after its maximum wear has been reached. Dependent on the setting of the parameter "Stop at end of stepper" (BOS), the timer goes into "block", sends the message "tipdressing necessary" (see page 6-22), and waits for the acknowledgment "Tips have been dressed".

 **The time the robot recognizes "Tipdress prewarning" depends on the way it is programmed. The relevant robot inputs are often scanned only before welding of a new part and not after each spot. This behavior requires the following:**

- **The time between the output of the signal "Tipdress Request" and the maximum wear must be sufficiently set. Only this way it can be guaranteed that the part can be completely welded before reaching the maximum wear.**

The robot tells the timer that the electrode dressing procedure is finished by sending the message "Tips have been dressed".


As long as a new electrode tipdressing process is still possible at this point, the timer reacts to a positive signal edge at the "Tips have been dressed" acknowledgement as follows:

1. The tipdress counter of the relevant electrode number will be incremented.
2. The wear counter of the relevant electrode number will be reset to value 0.
3. The "Tipdress prewarning" output signal (see page 6-22) or "Tipdressing necessary" (see page 6-22) is reset.

I/O Signal Descriptions

**Example** The following settings are used:

- %I Stepper: On
- Stepper: active (if Stepper final current > basic current)
- Tipdressing: On (if max. tipdressing steps > 0. Here: max. tipdressing steps = 3)
- Stepper: active (if Stepper final current > basic current)
- Wear factor: 1.0
- Wear start section (offset): 0
- Wear stepper section: 100
- Max. wear: 100 (= wear stepper section - offset)
- Tipdressing inquiry: 10 (= 10 before max. wear)
- Prewarning: 30 (= 30 before max. wear)



Example: Tipdressing schedule

### 6.1.11 Acknowledgement 'Tips have been replaced'

First, the timer informs the robot via the output signal "Prewarning" (see page 6-23) that an electrode must be exchanged "soon".

- ☞ **Prior to the end of stepper (see page 6-23), the time for outputting the signal "Prewarning" is parameterizable (BOS) as wear. If tipdressing is active, the timer will output "Prewarning" signal only if no further tipdressing is permissible.**

**It depends on the parameterization of the timer whether or not further welds are still possible after exceeding the end of stepper (parameter "stop at end of stepper").**

If the robot recognizes the "Prewarning", in ideal circumstances, it moves the gun to the gun maintenance position in order to exchange the electrodes.

- ☞ **The time the robot recognizes "Prewarning" depends on the way it is programmed. The relevant robot inputs are usually scanned only before welding of a new part and not after each spot. This behavior requires the following:**

- **The time between the output of the signal "Tipdressing prewarning" and the end of stepper must be sufficiently set.**
- **The function "Stop at end of stepper" is switched off.**

**Only this way it can be guaranteed that the part can be completely welded before reaching the maximum wear.**

The timer must be informed about the executed electrode exchange either via "Electrodes have been replaced" or via GUI (BOS).

The timer reacts to a positive signal edge at the "Electrodes have been replaced" acknowledgement as follows:


1. The tipdress counter of the relevant electrode will be reset.
2. The wear counter of the relevant electrode number will be reset to value 0.
3. The "Tipdress prewarning" or "End of stepper" is reset.
4. When "Tipdressing of new electrodes" is activated (initial dressing; please refer to page 3-27), the output "Initial dressing request" (see page 6-22) will be activated.

- ☞ **Electrode "0" can be reset only via GUI (BOS).**

I/O Signal Descriptions

**Example** The following settings are used:

- %I Stepper: On
- Stepper: active (if Stepper final current > basic current)
- Tipdressing: On (if max. tipdressing steps > 0. Here: max. tipdressing steps = 3)
- Stepper: active (if Stepper final current > basic current)
- Wear factor: 1.0
- Wear start section (offset): 0
- Wear stepper section: 100
- Max. wear: 100 (= wear stepper section - offset)
- Tipdressing inquiry: 10 (= 10 before max. wear)
- Prewarning: 30 (= 30 before max. wear)
- Stop at End of Stepper: Off



Example: Electrode replacement

## I/O Signal Descriptions

**6.1.12 Acknowledgement 'Tips have been replaced' x**

First, the timer informs the robot via the output signal "Prewarning tip replacement" (see page 6-15) that an electrode must be exchanged "soon".

When the robot recognizes "Prewarning tip replacement", it must replace the tip – at the latest after its programmable tipdress counter end value has been reached. Otherwise, the timer will go into "block" and wait for acknowledgement "Tips have been replaced".

The robot tells the timer that the tip replacement procedure is finished by sending the message "Tips have been replaced".

The timer reacts to a positive signal edge at the "Tips have been replaced" acknowledgement as follows:

1. The corresponding tipdressing counter is reset to value 0.
2. The relevant output signal "Prewarning tip replacement" (see page 6-15) or "Tip replacement" is reset.
3. Any start inhibit (timer block) is cancelled.

I/O Signal Descriptions

Notes:

## I/O Signal Descriptions

## 6.2 Output Signals

### 6.2.1 Alphabetical Overview

Signal name	Page
CONTROL READY	6–19
SHEET THICKNESS	6–17
SHEET THICKNESS TOLERANCE	6–17
WELD COMPLETE (WC)	6–18
TIPDRESSING REQUEST x	6–22
TIP REPLACEMENT x	6–16
TIPDRESS PREWARNING x	6–22
END OF STEPPER ELECTRODE x	6–23
WELD/NO WELD	6–21
WITHOUT REGULATION AND WITHOUT MONITORING FUNCTION	6–22
WITHOUT MONITORING FUNCTION	6–21
AUTOMATIC PROGRAM SELECTION ACTIVE	6–22
PROP. VALVE SELECTION	6–16
SPOT SELECTION TAKEN OVER	6–23
WELDING FAULTS	6–20
STATUS	6–24
TIPDRESS PREWARNING x	6–23
PREWARNING TIP REPLACEMENT x	6–15

### 6.2.2 Prewarning Tip Replacement x

Informs the PLC/the robot that the tip in question (1, 2, 3, or 4) requires replacement as soon as possible.

The signal is set when the respective parameterizable tip prewarning value has been reached.

The "Tips have been replaced" acknowledgement (see page 6–13) resets "Prewarning tip replacement".

 For more information, refer to "Tip Replacement" on page 3–29.

I/O Signal Descriptions

### 6.2.3 Tip Replacement x

Informs the PLC/the robot that the cutters of the tip in question (1, 2, 3, or 4) require replacement as soon as possible.


The signal is set when the parameterizable value "Max. tip wear" Has been reached; it can be reset by means of the programming device (BOS) or via the "Tip replacement" acknowledgment (see page 6-13).

 For more information, refer to "Tip Replacement" on page 3-29.

### 6.2.4 Prop. Valve Selection

By means of the 8 output signals "Prop. Valve selection 01" to "Prop. Valve selection 128", the timer transmits the programmed manipulated power variable via DeviceNet.

To this end, the maximum possible manipulating range at X2 (see page 5-7) is subdivided into 256 discrete steps, and the active output signal of X2 is output as binary-coded pressure stage.




Binary-coded output of the active pressure stage

 The signals are used in connection with the "Sheet thickness" and "Sheet thickness tolerance" signals to active servotongs.

## I/O Signal Descriptions

## 6.2.5 Sheet Thickness


Via the 8 output signals "Sheet thickness 01" to "Sheet thickness 128", the timer transmits the programmed sheet thickness in binary code via DeviceNet to the electronic tongs system. In this way, the closing motion of the tongs in a short distance of the material surface can be influenced in such a way that the electrodes make contact "softly".



Binary-coded output of sheet thickness

## 6.2.6 Sheet Thickness Tolerance

Via the 8 output signals "Sheet thickness tolerance 01" to "Sheet thickness tolerance 128", the timer transmits the programmed sheet thickness tolerance in binary code via DeviceNet to the electronic tongs system. In connection with the transmitted sheet thickness (see Chap. 6.2.5), the closing motion of the tongs in a short distance of the material surface can be influenced in such a way that the electrodes make contact "softly".



Binary-coded output of sheet thickness tolerance

## I/O Signal Descriptions

## 6.2.7 Weld Complete (WC)

The output signal "Weld complete" informs the connected peripherals (PLC/robot) about the termination of the welding process.

This way, the next step of the working process can be initiated. The logics for generating a WC is activated in the following cases:

1. in case of single spot welding (e.g. in connection with robots) after each spot
2. in case of seam mode (e.g. roll seam welds) at the end of the seam
3. upon "set WC" (possible only via BOS)
4. upon "Reset Fault with WC" (see page 6-7).

 **How long the WC remains set, depends on the input signal "Start". See "WC period".**

The 1. and 2. case give you the possibility to adjust the WC to your application via parameterization (BOS).

- Automatic output of the WC only after a proper weld, or even after an erroneous weld.
- Time at which the WC should be set (see "WC starting time").


### WC period

Normally, the timer resets the signal "Weld complete" automatically if it recognizes a negative edge at the input "Start".

Nevertheless, there are situations possible in which the "Start" signal is reset prior to setting the WC. Here, a triggering on the negative edge of "Start" is not possible. Therefore, when setting the WC, the timer checks whether "Start" is still pending and reacts as follows:

"Start" is set: WC will be reset only after a negative edge of "Start"

"Start" is not set: WC will be reset after the parameterized WC period (GUI (BOS); default: 20 ms).



*WC period depends on signal "Start"*

## I/O Signal Descriptions

☞ **The programmed WC period also runs during start simulation (BOS)!**

**WC starting period**


The time, at which "Weld complete" shall be output, is – **in relation to the end of the HLD** – parameterizable within the following limits:

- with PSI:  $\pm 1000$  ms
- with PST:  $\pm 50$  cycles.

Restriction: The earliest possible output of the WC is possible after 20 ms or 1 cycle after the start of the HLD.

Default setting: End of HLD minus 20 ms or 1 cycle (see "example").

This way, the starting time of the WC can be anticipated and moved into the HLD time as well as delayed.



*Moving of WC starting time*

**Example:** "Fast robot communication"

If "Weld complete" is used as a command for positioning the robot to the next spot, you can compensate constant response times (caused by signal processing in the robot, drive, or PLC area) by anticipating the starting time of the WC. This will lead to shorter clock times.

**CAUTION**

**Damage to the installation caused by positioning movements with a closed gun are possible!**

**Therefore, make sure that the electrodes are already open when the robots' drives start!**

**6.2.8 Control Ready**

The output signal indicates that the timer is ready to weld. In this state,

- you can start a new welding schedule (see page 6-2)
- the LED READY at the timer's front is lit (see page 2-8).

## I/O Signal Descriptions

If an error occurs, the timer goes into "Block".

In this state,

- it is not possible to start a welding process (schedule)
- the LED READY at the timer's front goes off
- the output signal "Control Ready" will be reset.

 **Error and status messages are listed in the "Error list PS5000/PS6000" (No.: 1070 087 000).**

In order to restore the "Ready"-state of the timer after an error, you have the following possibilities at your disposal:

1. Push the reset button at the timer's front (see page 2-8) or
2. a positive edge of the "Fault reset" input signal (refer to page 6-6) or
3. a positive edge at the "Reset fault with WC" input signal (refer to page 6-7) or
4. a positive edge at the "Reset fault with spot repeat" input signal (refer to page 6-8) or
5. operation via software ("Reset fault", "Reset fault with WC", and "Reset fault with spot repeat" are also possible via BOS).

## 6.2.9 Welding faults

If an error occurs during welding,

- the timer sets the output "Welding Fault" and
- deletes the output signal "Control Ready" (refer to page 6.2.8).

Further welding processes can only be started, when all pending errors are eliminated and acknowledged (reset). Please refer to "Reset fault" on page 6-6.

 **Error and status messages are listed in the "Error list PS5000/PS6000" (No.: 1070 087 000).**

 **It depends on the parameterization of the timer (BOS; fault allocation) whether an event is interpreted as a fault or a warning.**

## I/O Signal Descriptions

## 6.2.10 Weld/No Weld

Via the output signal "Weld/No weld" you can check whether the currently selected welding program is executed

- with current (output is set) or
- without current (output is not set).

During a welding program you can work **with current** only if

- "Weld on External" (see page 6-5) is set and
- Weld internal (parameterizable via BOS) and
- program-related weld (parameterizable via BOS) have been switched on.

I.e. that "Weld/No weld" is the result of an AND operation of all 3 mentioned conditions.

## 6.2.11 Without Monitoring

Via this output signal you can check whether the currently selected welding program is executed

- without current monitoring (output is set) or
- with current monitoring (output is not set).



### CAUTION

**Incorrect welding may occur!**

**If current monitoring is switched off, actual current values that lie outside the permissible tolerance bands do not lead to a welding fault!**

**Therefore, make sure that all weldings that might be executed "without monitoring" are checked sufficiently!**

---

During the process of a welding program, current monitoring is active only in the following cases ("Without monitoring" is not set):

- the timer-related Monitoring stopped (effective for all programs) is switched off
- the program-related current monitoring is active for **all** weld times.

## I/O Signal Descriptions

## 6.2.12 Without Regulation and Without Monitoring

Via the "Without regulation and without monitoring" output signal, you can check – while monitoring and regulation inhibit are deactivated for the entire module – whether all welding programs are executed with deactivated start inhibit and activated weld (firing)

- with current monitoring, and
- in CCR mode.

The output signal is not set only if exactly this is the case. In all other situations, the output signal will be set.

**CAUTION**

**Incorrect welding may occur!**

**If current monitoring is switched off, actual current values that lie outside the permissible tolerance bands do not lead to a welding fault!**

**Therefore, make sure that all weldings that might be executed "without monitoring" are checked sufficiently!**

---

## 6.2.13 Automatic Program Selection Active

Mirrors the state of the input signal of the same name (see page 6-4).

## 6.2.14 Tipdress Prewarning x

Informs the PLC/robot that the active electrode must be tipdressed as soon as possible.

If further electrode tipdressing is still allowed at this point, the signal will be set when a parameterizable wear value is reached.

The acknowledgement "Tips have been dressed" resets "Tipdress prewarning".



**For more information, refer to "Electrodes have been replaced x" on page 6-9 ff.**

## 6.2.15 Tipdressing Request x

Informs the PLC/robot that the relevant electrode must be tipdressed.

If further electrode tipdressing is still allowed at this point, the signal will be set when a parameterizable wear value is reached.

The acknowledgement "Tips have been dressed" resets "Tipdressing request x".

## I/O Signal Descriptions

 **For more information, refer to "Electrodes have been replaced" on page 6–9 ff.**

## 6.2.16 Prewarning x

Will be set when a parameterizable wear value is reached. The output signal informs the PLC/robot that the active electrode will reach the end of stepper soon and that the electrode must therefore be replaced.

A positive edge of "End of stepper" resets "Prewarning x".

 **For more information, refer to "Electrodes have been replaced x" on page 6–11 ff.**

## 6.2.17 End of Stepper Electrode x

Informs the PLC/robot that the active electrode has reached the end of stepper.

The acknowledgement "Tips have been replaced x" resets "End of stepper electrode x".

 **It depends on the parameterization of the timer whether or not further welds are still possible after exceeding the end of stepper (parameter "stop at end of stepper").**

 **For more information, refer to "Electrodes have been replaced x" on page 6–11.**


## 6.2.18 Spot Selection Taken Over

Reaction to the "Spot selection ready" input signal.  
See page 6–4 for information on the functions.

I/O Signal Descriptions

### 6.2.19 Status

Via the "Status 1" through "Status 128" outputs, the control transmits its current status in binary code via INTERBUS-S.



Binary coded output of current timer status

Currently, the following messages are defined:

Code (dec)	Description
00	OK
01	Weld off, internal
02	Weld off, external
03	Faulty program selection
04	Faulty spot selection
05	Sequence inhibited
06	No weld program
07	
08	
09	
0A	Battery error
0B	Memory cleared
0C	Hardware error
0D	External temperature too high
0E	Stop circuit open / no +24V
0F	Main switch triggered / Current passed without command
10	measuring circuit open
11	short circuit of measuring circuit
12	No primary voltage in the 1. half cycle
13	

## I/O Signal Descriptions

Code (dec)	Description
14	
15	No current (standard mode)
16	No current 1. weld time (mix mode)
17	No current 2. weld time (mix mode)
18	No current 3. weld time (mix mode)
19	Current too low (standard mode)
1A	Current too low 1. weld time (mix mode)
1B	Current too low 2. weld time (mix mode)
1C	Current too low 3. weld time (mix mode)
1D	Current too high (standard mode)
1E	Current too high 1. weld time (mix mode)
1F	Current too high 2. weld time (mix mode)
20	Current too high 3. weld time (mix mode)
21	Current too low for a series of welds (standard mode)
22	Current too low for a series of welds 1. weld time (mix mode)
23	Current too low for a series of welds 2. weld time (mix mode)
24	Current too low for a series of welds 3. weld time (mix mode)
25	Time too short (standard mode)
26	Time too short 1. weld time (mix mode)
27	Time too short 2. weld time (mix mode)
28	Time too short 3. weld time (mix mode)
29	Time too long (standard mode)
2A	Time too long 1. weld time (mix mode)
2B	Time too long 2. weld time (mix mode)
2C	Time too long 3. weld time (mix mode)
2D	Minimum phase angle 1. weld time
2E	Minimum phase angle 2. weld time
2F	Minimum phase angle 3. weld time
30	Maximum phase angle 1. weld time
31	Maximum phase angle 2. weld time
32	Maximum phase angle 3. weld time
33	Full sine 1. weld time
34	Full sine 2. weld time
35	Full sine 3. weld time

I/O Signal Descriptions

Notes:

Maintenance

## 7 Maintenance

### 7.1 Battery

In order to buffer the RAM (contains the entire parameterization with all welding programs) and the internal clock, an integrated battery is provided.

Type of battery: Lithium  
Size: AA  
Voltage: 3.6 V  
Order No.: 1070 914446

When the remaining battery capacity becomes critical, the timer generates an error message or warning (parameterizable). The LED BATTERY FAULT at the timer's front is lit (see page 2–8).

If the event has been defined as an error message, a welding process is not possible in this state.

- ★ Include battery replacement in the regular maintenance schedule of the installation! Replacement: at least every 2 years.



#### CAUTION

**Damage caused by improper handling of electronic components! Therefore, batteries must be replaced by authorized technical personnel only!**

---



#### CAUTION

##### Data loss!

**Without a pending supply voltage and after removal of the battery, data back-up is guaranteed for up to 24 hours only. Therefore, always have at your disposal a new battery and insert it immediately upon removal of the old one.**

---

#### *Battery replacement*

The battery may be exchanged while the timer is running.

1. Turn the battery cover on the timer's front (see page 2–8) to the left and remove the old battery.
2. Insert the new battery correctly. For correct polarity, please refer to the illustration on the front of the timer.
3. Now, close the battery compartment with the battery cover.

### 7.2 Firmware

The timer will be shipped with the latest firmware installed. Via the programming device (BOS), the version of the firmware can be displayed.

## Maintenance

In rare cases, it may be necessary to update the firmware.

**CAUTION**

**Risk of damage by improper handling.**

**Firmware updates may therefore be carried out upon our instruction and by authorized technical personnel only!**

For a firmware update, you need

- a pointed object for operating the "boot" button (for position, refer to page 2–8),
- a PC with "WinBlow" software,
- a suitable connecting cable (timer <-> PC, for wiring, refer to page 5–13) and
- a data carrier (floppy disk, CD) with the corresponding firmware.

★ Proceed as follows:

1. Connect one of the PC's V24 interfaces (COM1 or COM2) to the timer's X1.
2. Start the "WinBlow" software. Select the desired language and the V24 interface.
3. Insert a data carrier with the firmware into the PC. Select the path and file name of the firmware. Firmware files carry the extension ".hex".
4. Click on "Backup – Load Firmware – Restore".  
You are prompted to set the bootstrap mode on the unit.

☞ **Further welding processes are not possible anymore!**  
**If you want to exit the bootstrap mode at this point, you have to interrupt the timer's 24 V<sub>DC</sub> power supply (see page 5–3).**

5. Push the recessed "boot" button on the front of the timer. This way, the unit is switched from operating to bootstrap mode. This condition is indicated by the "Boot" LED above the button.

☞ **After having initiated the next step, do not interrupt the power supply until the complete firmware has been loaded!**

6. Confirm at the PC that the bootstrap mode has been activated. The firmware is now being loaded. A bar indicates the current status of the process.
7. Wait until the PC indicates that the transfer is complete.
8. Interrupt the timer's 24 V<sub>DC</sub> power supply for at least 5 seconds (remove X4). Then reinstall X4.  
The timer is booted with the new firmware.
9. Check the firmware version via the programming device (BOS).

Maintenance

Notes:

## 8 Status and Error Messages

If timer-relevant events occur during operation, you will be informed by the timer.

Primarily you can differ between

- faults and
- warnings.

### In case of faults

- it is not possible to start a welding process (schedule)
- the LED READY at the timer's front goes off (see page 2-8)
- the serial output signals "Status" (refer to page 6-24) show important higher level causes for errors
- the output signal "Control Ready" will be reset (refer to page 6-19).

### In case of warnings

- other welding processes can still be executed.

 **It depends on the parameterization of the timer (BOS; fault allocation) whether an event is interpreted as a fault or a warning.**

Errors as well as warnings can be "self-acknowledging".

"Self-resetting" means that the timer automatically deletes such events after elimination of the error's or warning's cause. They do not require a manual "Reset fault".

Examples for self-resetting faults:

- Stop circuit open / no 24 V
- Power voltage off / too low

The timer uses code numbers to signal faults and warnings. Only in the programming device or in the line PC, the code numbers are substituted by text. This saves memory resources in the timer and reduces the time necessary for communication.

 **Error and status messages are listed in the "Error list PS5000/PS6000" (No.: 1070 087 000).**

## Status and Error Messages

Notes:

CE Declaration of Conformity

# 9 CE Declaration of Conformity

EG Konformitätserklärung  
EC declaration of conformity  
Déclaration "CE"

Hiermit erklären wir, daß unser Produkt, Typ: PST 6000  
 We hereby declare that our product, type:  
 Nous déclarons par la présente que notre produit, type: Typen gemäß beiliegender Liste

folgenden einschlägigen Bestimmungen entspricht:  **Maschinenrichtlinie (89/392/EWG, 91/368/EWG, 93/68/EWG und 93/44/EWG)**  
 complies with the following relevant provisions: **Machinery Directive (89/392/EEC, 91/368/EEC, 93/68/EEC and 93/44/EEC)**  
 correspond aux dispositions pertinentes suivantes: **Directive sur les machines (89/392/CEE, 91/368/CEE, 93/68/CEE et 93/44/CEE)**

**Niederspannungsrichtlinie (73/23/EWG, 93/68/EWG und 93/44/EWG)**  
**Low voltage Directive (73/23/EEC, 93/68/EEC and 93/44/EEC)**  
**Directive sur les basses tensions (73/23/CEE, 93/68/CEE et 93/44/CEE)**

**EMV-Richtlinie (89/336/EWG, 93/68/EWG und 93/44/EWG)**  
**EMC Directive (89/336/EEC, 93/68/EEC and 93/44/EEC)**  
**Directive EMV (89/336/CEE, 93/68/CEE et 93/44/CEE)**

Angewendete harmonisierte Normen, insbesondere:  
 Applied harmonized standards, in particular:  
 Normes harmonisées utilisées, notamment:  
EN 50081-2  
EN 50082-2  
EN 50178  
EN 60204-1

Angewendete nationale Normen und technische Spezifikationen, insbesondere:  
 Applied national technical standards and specifications, in particular:  
 Normes et spécifications techniques nationales qui ont été utilisées, notamment:

Formular 10/007/4876 - 102/W611

29.11.99 TS TED  
 Datum / Unterschrift / Technische Betriebsleitung

25.11.1999 AL AL/ELS  
 Datum / Unterschrift / Entwicklungsleitung

**BOSCH** 

Robert Bosch GmbH  
 Geschäftsbereich Automationstechnik  
 Betrieb Erbach  
 Postfach 1162  
 D-64701 Erbach/ Odw.

Sach-Nr. 1070 80444 - 102\_474

CE Declaration of Conformity

EG Konformitätserklärung  
EC declaration of conformity  
Déclaration "CE"

Hiermit erklären wir, daß unser Produkt, Typ: PSI 6000

We hereby declare that our product, type:

Nous déclarons par la présente que notre produit, type: Typen gemäß beiliegender Liste

folgenden einschlägigen Bestimmungen entspricht:

complies with the following relevant provisions:

correspond aux dispositions pertinentes suivantes:

**Maschinenrichtlinie** (89/392/EWG, 91/368/EWG, 93/68/EWG und 93/44/EWG)  
Machinery Directive (89/392/EEC, 91/368/EEC, 93/68/EEC and 93/44/EEC)  
Directive sur les machines (89/392/CEE, 91/368/CEE, 93/68/CEE et 93/44/CEE)

**Niederspannungsrichtlinie** (73/23/EWG, 93/68/EWG und 93/44/EWG)  
Low voltage Directive (73/23/EEC, 93/68/EEC and 93/44/EEC)  
Directive sur les basses tensions (73/23/CEE, 93/68/CEE et 93/44/CEE)

**EMV-Richtlinie** (89/336/EWG, 93/68/EWG und 93/44/EWG)  
EMC Directive (89/336/EEC, 93/68/EEC and 93/44/EEC)  
Directive EMV (89/336/CEE, 93/68/CEE et 93/44/CEE)

Angewendete harmonisierte Normen, insbesondere:

Applied harmonized standards, in particular:

Normes harmonisées utilisées, notamment:

- EN 50081-2
- EN 50082-2
- EN 50178
- EN 60204-1

Angewendete nationale Normen und technische Spezifikationen, insbesondere:

Applied national technical standards and specifications, in particular:

Normes et spécifications techniques nationales qui ont été utilisées, notamment:

Formular 1070074976 - 102W611

29.11.99 NS TELS  
Datum / Unterschrift / Technische Betriebsleitung

25.11.1999 AT/EWS  
Datum / Unterschrift / Entwicklungsleitung

**BOSCH**



Robert Bosch GmbH  
Geschäftsbereich Automationstechnik  
Betrieb Erbach  
Postfach 1162  
D-64701 Erbach/Odw.


Sach-Nr. 1070 80297 -101 474

Timer Diagrams

## 10 Timer Diagrams


The following pages contain some examples of timer diagrams.

Timer Diagrams



Example for normal schedule, single spot

Timer Diagrams



Example for normal schedule, seam mode

## Timer Diagrams

Notes:

## Appendix

**A Appendix****A.1 Abbreviations**

AC	Alternating current	HOT	Hold-open time. Time between two welding points in which the solenoid valve is not activated. Only relevant for the Serial spot operating mode.
DC	Direct current	PE	Protective Earth.
CSE	Electrostatic sensitive assemblies and components	PU	Programming unit / welding processor
EMC	Electromagnetic compatibility	PHA	Phase angle.
IS	Individual-spot operating mode: for automatic and manual systems	PSG	Transformer-rectifier unit for PSI types.
ESD	Electrostatic discharge. Abbreviation for all designations that are concerned with electrostatic discharge, e.g. ESD protection, ESD-sensitive.	3.CT	Cooling time. Time between the current pulses/blocks (1st, 2nd, 3rd CT).
DST	End slope time. Time in which the LST drops to the end of the 2nd WLD.	RO	Relay output.
ext.	External, e.g. related to +24 V current for signal elements (switches) and controlling elements (valves) outside of the control.	SCV	Scale values. Measure for the electrical phase angle.
WC	Stepping contact. The signal is issued after the spot is completed.	Slope	Current ramp. Current rises/falls from an initial to a final value.
MST	Main switch trigger	SS	Serial spot. Operating mode for manually operated systems.
IMP	Impulse number. Number of impulses that form the 2nd WLD.	PLC	Programmable logic control.
kA	Kiloamperes	WT	Weld timer. Also referred to as timer or resistance weld control.
KSR	Constant current control. Keeps the current in the welding circuit constant.	UST	Initial slope time. Time in which the LST increases from the start of the 2nd WLD.
CVC	Constant voltage control. Controls power supply voltage variations.	Stepper	Current stepping for compensation of electrode wear
POW	General abbreviation for Power; can refer to SV (scale values) or kA.	WLD	Current time. There are three types: 1st WLD (preheating current time), 2nd WLD (main welding current time) and 3rd WLD (postheating current time). The times and power of all 3 current times can be programmed differently. Impulses and slopes can be programmed only in the 2nd WLD.
PSU	Power section unit (thyristor or inverter)	Temp.	Temperature.
SV	Solenoid valve. Activation of cylinders to close the electrodes.	Monit. cont.	Monitoring contact. E.g. for monitoring of the pressure cylinder (which closes the electrodes) or of the electrode position (e.g. "Tongs closed").
SLC	Supply load control. Monitors and changes the load in the power supply	SQZ	Derivative-action time. Time that runs before the welding time. The electrodes squeeze together the parts to be welded.
HLD	Holding time. Time after the last under-current time, during which the parts to be welded can cool off.	PHT	(pre-heating time) Also called the 1st UCT
PHT	Post-heating time. Also called the 3rd WLD	Weld/no weld	Weld/No weld The firing pulses for triggering the power section are switched on and off.

Appendix

## A.2 Index

### Symbols

(pre-heating time), 3–5  
%I Stepper, 3–27

### Numbers

1. Half cycle, 3–22

### A

Acknowledgement 'Tips have been dressed', 6–9  
Acknowledgement 'Tips have been replaced', 6–13  
Acknowledgment "Tips have been replaced", 6–11  
Air pressure, 4–1  
Assembly, 1–6  
Automatic program selection active, 6–4, 6–22  
Automatic spot repetition, 3–23

### B

Backup battery, 4–1  
Battery, 4–1  
Battery replacement, 7–1

### C

Cables, 1–9  
CC, 3–12  
CE mark, 1–14, 9–1  
Code numbers, 8–1  
Communication, 5–14  
Condensation, 4–1  
Conditional permissible tolerance band, 3–16  
Connection, 5–1  
Constant current regulation, 3–12, 5–10  
Control ready, 6–19  
Cooling, 2–2  
Cooling water, 1–8  
    Chlorides, 1–8  
    Degree of hardness, 1–8  
    Insoluble substances, 1–8  
    Nitrates, 1–8  
    pH value, 1–8  
    Sulfates, 1–8  
Corrections, 3–35  
CSE, 1–12, A–1  
CT (cool time), 3–9, 3–10  
Current blocks, 3–4  
Current downslope time (DST), 3–7  
Current input, 4–2  
Current monitoring:, 3–15  
Current passed without command, 5–12  
Current prewarning and limitation, 3–14  
Current scaling, 3–33

### D

Degree of protection, 4–1  
DeviceNet Connection, 5–16  
Diagrams, 10–1  
Dimensions, 2–2  
Diode monitoring, 3–36

### E

Electrical Connection, 1–9  
Electrode force, 3–29  
Electrode life (Stepper), 3–28, 6–23  
Electrode maintenance, 3–25  
Electrostatic sensitive assemblies and components,  
    1–12  
EMC, 5–1  
EMERGENCY–STOP facilities, 1–9  
End of stepper electrode x, 6–23  
Error reset with spot repeat / WC, 6–8  
Error reset with WC, 6–7  
errors, 8–1  
ESD, A–1  
    workplace, 1–12  
    protection, 1–12  
Ethernet, 4–1

### F

Fade-out time, 3–18  
Failure of the sensor, 5–10  
Fan connection, 5–13  
Features, 2–2  
Fieldbus module, 2–6  
Firmware, 7–1  
Firmware update, 7–2  
Force, 3–29  
Force profile, 3–30  
Force scaling, 3–31  
Force Stepper, 3–30

### G

Grounding bracelet, 1–12

### H

Hardware, 2–6  
HLD (hold time), 3–10  
Humidity, 4–1

### I

I/O interface, 2–6  
I/O Module "DEV-NET", 2–10, 4–2, 5–14  
I/O module supply, 5–14  
Ignition on, external, 6–5

## Appendix

Impulse mode, 3-5

Input signals, 6-1

Installation, 1-6

Intended Use, 1-3

INTERBUS-PMS, 4-1

Interference suppression, 5-1

Interlock, 3-21, 6-2

**K**

KSR sensor, 5-9

**M**

Main components of a welding station, 3-1

Main switch trigger, 4-2, 5-11

Mains connection, 2-2

Maintenance, 1-12, 7-1

Measuring circuit test, 3-21, 5-11

Mixed operation

Monitoring, 3-17

Regulation, 3-11

Modifications, 1-2

Modifications by the user, 1-11

Monitoring, 3-15, 6-21

Monitoring modes, 3-17

**O**

offline, 2-5

online, 2-5

Operating temperature, 4-1

Operating voltage, 4-1, 4-2

Operation, 2-5

Output signals, 6-15

Overview, 2-1

**P**

PE, A-1

PHA, 3-11

Phase angle, 3-11

Post-heating time, 3-5

Power loss, 4-2

Power supply, 5-14

Pressure control, 4-1, 5-7

Prewarning, 3-28, 6-23

Prewarning table, 3-28

Prewarning tip replacement, 6-15

Primary circuit, 5-10

PROFIBUS-FMS, 4-1

Program selection, 6-3

Programming, 2-5

Programming unit, 5-13

Programs, 4-1

Prop. valve selection, 6-16

Proportional control valve, 5-7

**Q**

Qualified personnel, 1-4

Quality module, 2-6

**R**

Rated current, 4-1

RC element, 5-1

Regulation modes, 3-11

Repair, 1-12

Repeat factor, 3-16

Reset fault, 6-6

Retrofits, 1-11

Robots, 3-2

Roll seam, 3-3

RS232, 5-13

**S**

Safety instructions, 1-2

Scaling, 3-31

Schedule diagrams, 10-1

Seal weld, 3-3

Seam mode, 3-3

Secondary circuit, 5-10

Self-resetting, 8-1

Sheet thickness, 6-17

Sheet thickness tolerance, 6-17

Signal descriptions, 6-1

Signal outputs and inputs, 5-16

Single spot, 3-2

Slope, 3-7

Spare parts, 1-12

Spot repetition, 3-23

Spot selection, 6-3

Spot selection taken over, 6-23

SQZ (squeeze time), 3-9

Standard operation

Monitoring, 3-17

Regulation, 3-11

Start, 6-2

Starting current, 4-1

Status, 6-24

Stepper, 3-27

Stepper monitoring, 3-20

Stitch weld, 3-3

Storage, 4-1

Supply of external devices, 5-4

Supply of timer logics, 5-3

**T**

Testing work, 1-12

Time monitoring Monitor Stepper, 3-20

Timeout, 3-20

Timer Diagrams, 10-1

Timer front, 2-8

## Appendix

Tip replacement, 3-29, 6-13, 6-15, 6-16

Tip stepper, 6-16

Tip wear monitoring, 3-29

Tipdress prewarning, 6-22

Tipdressing, 3-27

Tipdressing of electrodes, 3-27

Tipdressing request, 6-22

Tips have been dressed, 6-9

Tips replacement, 6-11

Tolerance range, 3-15

Toroid input, 5-10

Trail current , 3-18

Type codes, 2-1

Types of welding modes:, 3-2

## U

Ultrasonic control board, 2-4, 2-6

UST (current upslope time), 3-7

## V

Voltage distribution, 5-4

Voltage source, 5-2

## W

Warnings, 8-1

Wear factor, 3-25

Wear monitoring for tips, 3-29

Wear per part, 3-25

Weld (firing), 6-21

Weld complete, 6-18

Weld transformer selection (PSI only), 3-35

Weld/No Weld, 6-21

Welding current, 2-2

Welding faults, 6-20

Welding splashes, 1-13

Without Monitoring, 6-21

Without regulation and without monitoring, 6-22

WLD (weld time), 3-5

Working safely, 1-13

## X

X1, 5-13

X10, 5-14

X11, 5-16

X12, 5-16

X13, 5-16

X2, 5-7

X3, 5-9

X4, 5-2, 5-3, 5-4, 5-13

X5, 5-4

X8, 5-11

Appendix

Notes:

Bosch Rexroth AG  
Electric Drives and Controls  
P.O. Box 13 57  
97803 Lohr, Germany  
Bgm.-Dr.-Nebel-Str. 2  
97816 Lohr, Germany  
Phone +49 (0)93 52-40-50 60  
Fax +49 (0)93 52-40-49 41  
service.svc@boschrexroth.de  
www.boschrexroth.com

